

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page 7786)

Set post cor. to secs. 26, 27, 34 and 35, from which
A Fir 14" dia., bears N.75°E., 39 lks. dist.
A Cedar 12" dia., bears S.40°E., 35 lks. dist.
A Fir 40" dia., bears S.35°W., 51 lks. dist.
A Fir 16" dia., bears N.62°W., 36 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7815)

The sec. cor., which is a post, greatly decayed, with marks nearly obliterated. I find the 4 original witness trees. I remove this post and set a Fir post, 4 ft. long, 4" sq., 24" in the ground, marked T31S S26 on NE.; R4W S35 on SE.; S34 on SW.; and S27 on NW. faces, with 2 notches on E. and 1 notch on S. edges, from which
A Fir 14" dia., bears N.75°E., 39 lks. mkd T31S R4W S26 BT
A Cedar 12" dia. bears S.40°E., 35 lks mkd T31S R4W S35 BT
A Fir 40" dia., bears S.35°W., 51 lks mkd. T31S R4W S34 BT
A Fir 16" dia., bears N.62°W., 36 lks. mkd T31S R4W S27 BT

Survey by H.L. Eppstein, County Surveyor - Wit: W.S. Crear, Geo. Spain - Dec. 23,, 1925 - Vol. 3 Pg. 246 (and "old" cor. book, Pg. 161)

Set 4" x 4" x 36" Oak stake from old BTs which were all in good condition, BTs are
A Fir 14", N.75°E., 39 lks.
A Cedar 12", S.40°E., 35 lks.
A Fir 40", S.35°W., 51 lks.
A Fir 16" N.62°W., 36 lks.

George Wenderoth, Deputy Co. Surveyor - Dec. 1947 - C.S. File 40/29; M 4-75

Found - 26" Fir, N.62°W., 23.7 ft.
14" Fir, N.75°E., 25.7 ft.
15" Cedar, S.40°E., 23.1 ft.
Drove 1¼" I.Pipe for the corner and mkd. the following BTs:
10" Fir, N.49°55'E., 56.2 ft.
9" Fir, S.81°12'E., 49.6 ft.
8" Cedar, S.25°44'W., 34.3 ft.

(Cont. Next Page)

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Jan/Feb. 1966 - C.S. File 54/20-16

Found - I.Pipe at sec. corner.
26" Fir now 28", N.62°W., 23.7 ft., good scar.
14" Fir N.75°E., 25.7 ft., face rotten.
15" Cedar now 17", S.40°E., 23.1 ft., good scar.
10" now 14" Fir, N.55°E., 56.2 ft., good scar. (Brg. should be N.51°E.)
9" now 15" Fir S.81°E., 49.6 ft., good scar.
8" now 14" Cedar S.26°W., 34.3 ft., scribe visible. (brg. should be S.62°W.)

Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 4 W
S 27 | S 26
S 34 | S 35
1966

(Set brass cap alongside iron pipe.)
All bearing trees in good condition.

Fd. and used in BLM Resurvey by Lynn M. Roseberry and Larry D. Evans, Cadastral Surveyors, under Group #778, surveyed July/Sept. 1972- (DCSO records Vol. 38 Page(s) 15470-71)