

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7819)

A Fir 16" dia., which I mark $\frac{1}{4}$ S on W. face, for $\frac{1}{4}$ sec. cor., from which

A Fir 14" dia., bears S.87°W., 17 $\frac{1}{2}$ lks. dist. mkd. $\frac{1}{4}$ S BT.

A Fir 13" dia., bears S.60 $\frac{1}{2}$ °E., 12 lks. dist. mkd. $\frac{1}{4}$ S BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - March 1966 - C.S. File 54/20-26

Found - Orig. 16" Fir corner tree, now stump, shows scar on W. face.

Orig. 14" Fir, now snag, S.87°W., 11.5 ft., shows good scar.

Orig. 13" Fir, now stump, S.60 $\frac{1}{2}$ °E., 7.9 ft., scribe visible.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 4 W

$\frac{1}{4}$ S22|S23

1966

Brass cap at West face of corner tree stump.

New BTs- 24" D.Fir S.11°W., 42.2 ft. scribed $\frac{1}{4}$ S22 CS BT.

35" D.Fir N.70°W., 35.5 ft. scribed $\frac{1}{4}$ S22 CS BT.

Found OK by Max Hull, Dec. 2003 - M143-48

Found OK by Max Hull, April 2006 - M150-45

BLM Dependent resurvey by A Bert Skeesick Cadastral Surveyor, & Robert H Browning, Surveying Technician under Group No 2300 surveyed Dec 2004/Jan 2005 - (DCSO rec Vol 56 Pgs 21975-6)

The $\frac{1}{4}$ sec. cor. of secs. 22 & 23, monumented with a sawed, decayed fir stump, 24" dia., with no marks visible, perpetuated by the Douglas County Surveyor's Office in 1966, from which the remains of the original bearing trees

A decayed fir stump, 12" dia., bears S.48 $\frac{1}{2}$ °E., 7.9 ft., with scribe marks $\frac{1}{4}$ S BT visible on an unhealed blaze. (Record, S.60°E.)

A decayed fir snag, size indeterminate, bears S.87°W., 11.6 ft., with no marks visible.

and accessories mkd. by the Douglas County Surveyor's Office

A root hole, bears S.7 $\frac{1}{4}$ °W., 42.6 ft., with fallen fir trunk, 24" dia. lying alongside, with no marks visible.

An iron post, 1 $\frac{1}{4}$ " dia., firmly set, projecting 10" above ground, bears S.89°37'53"W., 1.37 ft., with brass cap mkd. COUNTY SURVEYORS OFFICE T31S R4W $\frac{1}{4}$ S22 S23 1966.

continued next page

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 38" dia. bears N.72 $\frac{3}{4}$ °W. 36.4 ft. with a healed blaze
At the corner point

Drive a finned aluminum rod, 36" long, in. dia., 32" in the
ground, through the decayed fir stump, with aluminum cap mkd.

T31S R4W

$\frac{1}{4}$

S 22 | S 23

2005

from which

A fir, 10" dia., bears S.1°W., 17.3 ft., mkd. $\frac{1}{4}$ S22 BT.
At the request of the Douglas County Surveyors Office, I
removed the 1966 brass cap from the iron post, (leaving the
post in place) and replaced it with a plastic cap mkd.
DOUGLAS COUNTY SURVEYOR.