

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7823)

Set a stone 10x10x8 ins., 7" in the ground, for cor. to secs. 2, 3, 10 and 11, marked with 2 notches on E. and 5 notches on S. edges; from which

A Fir 7" dia., bears N.82°E., 35½ lks. dist. mkd. T31S R4W S2 BT.

A Fir 4" dia., bears S.44°E., 38½ lks. dist. mkd. T31S R4W S11 BT.

A Maple 6" dia., bears S.56°W., 17 lks. dist. mkd. T31S R4W S10 BT.

A Fir 8" dia., bears N.23°W., 21 lks. dist. mkd. T31S R4W S3 BT.

Survey by Robert M. Thompson, R.E. 3683 - For: Harbor Plywood Corp. - April 1, 1955 - C.S. File 41/378

Corner set by double proportion.

Set a 4" x 5 ft. Yew wood post firmly in the ground, from which

16" D.Fir S.22°50'W., 40.7 ft.

23" D.Fir N.10°10'W., 27.3 ft.

40" D.Fir S.13°40'E., 36.6 ft.

18" D.Fir N.74°20'E., 18.1 ft.

Fd. unrecorded I.P. at cor. & NE & SW BTs as recorded in 1955 renewal - NW BT gone due to logging - SE BT turned out. No trees close to mk - This corner lies on steep NE slope approx. 500 ft S of line Xing on Road - July 1970 - V. Tracy, DCSO - C.S. File 54/20

Douglas County Surveyors Office - M. Lenora Ladig and Peter L. Earle, crew - June 10, 1976 - C.S. File 59/15-17

Found - An unrecorded 1½" x 26" I. Pipe. (first noticed July 1970 by Tracy)

23" now 27" D.Fir bears N.10°10'W., 27.3 ft. Tree alive with well healed blaze.

40" now 41" D.Fir bears S.13°40'E., 36.6 ft. Tree alive with "31-4" in cut open blaze.

In July 1970, V.R.T. of DCSO stated he found the NE and SW BTs as recorded by Markham, with NW and SE BTs gone due to logging. I find NW and SE BTs as recorded with the NE and SW BTs gone.

(Cont. Next Page)

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

At true corner point, a 1" x 36" I.Pipe with brass cap stamped: Douglas Co. Surveyor

T 31 S R 4 W

S 3 | S 2

S 10 | S 11

1976

Placed 1½" I.Pipe on North side of cap.

Did not mark new trees as no good trees in area due to logging.

Carl Sweeden - For: Rome Creek Timber - July 2013 - M165-56

Found - 1976 DCSO 2½" brass cap up 0.20'

1½" iron pipe along side

43" D.Fir BT, N.1°W., (N.10°10'W.) 27.3', 2 tags

31" Fir BT stump, S.5°E. (S.13°40'E.) 38.6' (36.6'),
scribe vis.

New BT- 13" Maple BT, N.50°E., 2.73' to face, "T31S R4W SW
S2 BT", tagged

12" D.Fir BT, S.55°E., 19.48', "T31S R4W NW S11 BT",
tagged.