

PRIMARY CORNER DESCRIPTION Sec. Cor. for 11, 12, 13 and 14

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7808)

-----

Set a Fir post, 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 11, 12, 13 and 14, marked T31S S12 on NE.; R4W S13 on SE.; S14 on SW.; and S11 on NW. faces, with 1 notch on E. and 4 notches on S. edges, from which

- A Hemlock 8" dia., bears N.73°E., 84 lks. dist. mkd. T31S R4W S12 BT.
- A Fir 28" dia., bears S.31½°E., 13 3/4 lks. dist. mkd. T31S R4W S13 BT.
- A Fir 30" dia., bears S.3½°W., 42 lks. dist. mkd. T31S R4W S14 BT.
- A Laurel 4" dia., bears N.40 3/4°W., 55 lks. dist. mkd. T31S R4W S11 BT.

Survey by Robert M. Thompson, R.E. 3683 - Jan. 30, 1956 - C.S. File 42/200

-----

I find Fir BTs for secs. 13 and 14 down with scribing and axe work visible. No trees of Hemlock in sec. 12 or of Laurel in sec. 11.

I set a 2" x 4" Fir stake and scribe 4 new BTs as prescribed by law:

- 12" D.Fir N.40½°W., 23.2 ft.
- 10" D.Fir N.31°E., 38.1 ft.
- 16" D.Fir S.34°E., 69.1 ft.
- 40" D.Fir S.59½°W., 42.1 ft.

Douglas Co. Surveyors Office - Clell Goodwin; Gary Langlitz; M. Lenora Ladig, crew - Nov. 26, 1975 - C.S. File 57/39-19

-----

Found - An unrecorded 1½" x 20" flanged axle.

- An orig. 28" Fir now rotted stump bears S.31¼°E., 9.1 ft.
- A 17" D.Fir bears N.45°W., 24.3 ft. (call: N.40½°W., 23.2 ft.) alive and well healed.
- A 14" D.Fir bears N.31°E., 37.0 ft. (call: N.31°E., 38.1 ft.) alive and well healed.
- A 20" D.Fir bears S.34°E., 69.1 ft. alive and well healed.
- A 34" stump bears S.57½°W., 44.1 ft. (call: S.59½°W., 42.1 ft.)

At the corner, We SET a 1" x 30" I.P. with brass cap stamped: Douglas Co. Surveyor 1975

T 31 S R 4 W	
<u>S 11</u>	<u>S 12</u>
S 14	S 13

(Cont. Next Page)

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 600500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 11, 12, 13 and 14

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

We drive the axle in SW. of the corner.  
New BT - 9" D.Fir scribed "T31S R4W S14 CS BT" in a double  
blaze, bears S.40°W., 22.7 ft.

Fd. corner as per 1975 renewal D.Edwards - 5/2010 - M 160-63  
Fd. to be Ok, July 2012, R. Quimby - C.S. file 65/77-15