

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 640500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 12 and 13

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7809)

Set a Cedar post 4 ft. long, 4" sq., 24" in the ground, for 1/4 sec. cor. marked 1/4 S on N. face; from which
A Fir 12" dia., bears N.53 1/2°W., 38 lks. dist. mkd. 1/4 S BT.
A Fir 8" dia., bears S.47°W., 38 lks. dist. mkd. 1/4 S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. -
Wit: R.G. Boyd - Oct. 7, 1959 - C.S. File 42/391-41

Determined by O.B.T.:
15" Fir bears N.53°W., 25.0 ft., found scribe.
At corner point, SET 3/4" x 30" Iron pipe, from which
5" Laurel bears N.67°E., 23.0 ft. mkd. 1/4 S12 BT.
14" Laurel bears S.73°W., 27.0 ft. mkd. 1/4 S13 T31S R4W BT.
16" Fir bears S.46°W., 44.0 ft. mkd. 1/4 S13 BT.
Corner lies in small draw.

Douglas Co. Surveyors Office - Clell Goodwin; Gary Langlitz;
M. Lenora Ladig, crew - Nov. 25, 1975 - C.S. File 57/39-17

Found - 19" Fir with scribe marks visible in partially
healed blaze, bears S.46°W., 44.0 ft.
The tree found by Markham to be an orig. BT, is now
a 16" dead snag. We find no scribe marks in
partially healed blaze.
At the corner, We SET a 1" x 30" I.P. with brass cap stamped:
Douglas Co. Surveyor
T 31 S R 4 W
1/4 $\frac{S\ 12}{S\ 13}$
1975

There are no live trees big enough to scribe nearby. Compass
declination 20°E. We also find the remains of the Laurel in
the NW. quadrant with visible scribe marks in the bark but
are unable to accurately determine where it stood.

David Edwards - For: Roseburg Resources - 5/2010 - M 160-63

Found - Brass cap.
Old BTs gone.
New - 13" dia., Fir S.63°E., 14.5'
6" dia., Fir N.86°W., 14.8'
Set 6' steel post 2' west.