

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 100647

PRIMARY CORNER DESCRIPTION AP (Orig. Line Tree) Secs 6 & 1, T31-6

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Orig. GLO Survey - Geo. W. Hyde, Deputy Surveyor under contract # 54, dated Feb. 19, 1855 (DCSO records Vol. 19 Page(s) 7877)

Set- Fir, 36" dia. at 33.50 chs.

Fd. OK - Douglas County Surveyors - Oct. 1979 - RM 3-26

Douglas County Surveyors Office - Randall Smith & Stephen Flause - Feb. 25, 1997 - C.S. 64/74-8

Found- Orig. 1855 36' dia. D.Fir
4' dia. D.Fir found by DCSO in 1979. We are unable to substantiate this line tree (trees ?).
From the Orig. 1855 ¼ section corner between secs 1 & 6 we tied two trees. Bearing are based on compass readings. Original line notes from 1855 note the line tree as being at a change of slope in terrain.
Approx. 4' dia. broken and rotted stump, bears N.0½°W. 462' (no marks fd) From 1855 corner tree
Approx. 4' dia. dead & burnt D.Fir (no marks visible) is found at a break in slope of terrain. bears N.1°W., 434' ft. from 1855 corner tree.
(Rec. per RM 3-26 is N.0°35'38"W., 461.34'. Rec. per orig. 1855 is north 429)

BLM dependent resurvey by Daniel E. Weller, Cadastral Surveyor, under Group #1884, surveyed July/Sept 1998. (DCSO records Vol. 53 Page(s) 20478)

The remains of an original line tree, a badly burnt fir stump, 40" diam., with no marks visible, recovered by Douglas County Surveyor, in 1979, recorded in Douglas County Survey Map RM-3-26. This now becomes an Angle Point.

At the corner point

Set a boat spike, 8" long, in top center of stump.
from which

A fir, 25" diam., bears N.5°E., 106 lks., mkd. X BT.

A stainless steel post, 28" long, 2½" diam., set 22 in the ground for a reference monument, bears N.52 3/4°W., 6.2 lks., with brass cap mkd. RM S1 4.1 FT TO COR 1998 and an arrow pointing to the cor.