

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W. P. Wright, under Contract #281 dated May 16, 1878 (DCSO records Vol. 19 Page(s) 7890)

Set post 2 x 4 ins. by 4 ft. long in mound of rock for ¼ sec. cor., from which
A Fir 21" dia., bears N.39°E., 30 lks. dist.
A Fir 30" dia., bears N.65°W., 21 lks. dist.

Douglas Co. Surveyors Office - George J. Wenderoth, Deputy - May 23, 1958 - C.S. File 49/92-3

Found this corner and drove 1" Iron pipe for corner.
40" Fir N.65°W., 13.9 ft., good.
43" Fir N.39°E., 19.8 ft., good.

Cor. Fd. OK, DCSO by John Powell, May 966

BLM Corrective Resurvey - John Jelley, Lynn Roseberry, Floyd Brooks, Under Group #s 320 and 614, - Surveyed June 1966 through May 1968. (DCSO records Vol. 35 Page(s) 14370)

The ¼ sec. cor., perpetuated and recorded by G.J. Wenderoth, in 1958, monumented with an iron pipe 1" dia., protruding 8" above ground, firmly set, from which the original bearing trees:

A Fir 44" dia., bears N.39°E., 30 lks. dist., with a healed blaze.
A Fir 42" dia., bears N.65°W., 21 lks. dist., with a healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. dia., 24 ins. in the ground, with brass cap mkd: T 31 S R 5 W

¼ $\frac{S\ 4}{S\ 9}$

1966

from which a new bearing tree

A Fir 12" dia., bears S.21°E., 39 lks. mkd. ¼ S9 BT.

Deposit the iron pipe alongside the iron post.

Ron Quimby - For: C & D Lumber Co. - Nov. 2014 - M166-22

Found - Brass cap per 1966-1968 BLM resurvey

45" Fir N.39°E., 19.8' healed face

22" Fir S.21°E., 25.7' healed face

50" Fir N.65°W., 13.9' healed face

New - 39" Fir S.74°W., 22.6' scribed "¼ S4 BT"