

TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 31; & 36 of T31-7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - George W. Hyde under Contract #54 dated Feb. 19, 1855 (DCSO records Vol. 19 Page(s) 7946)

-----  
Set ¼ sec. post, from which  
A Fir 4" dia., bears S.26°W., 7 lks. dist.  
A Fir 12" dia., bears N.49°E., 14 lks. dist.

W.H. Byars, under contract # 448 survey dated June 13, 1882 (DCSO records Vol. 19 Page(s) 7951)

-----  
Unable to find old corner or traces thereof, therefore, Set a Fir post, 40" long, 3" sq., 20" in the ground, mkd. ¼ S on W. side for the ¼ sec. cor., from which  
A Fir 16" dia., bears N.58°E., 30 lks. dist., mkd. ¼ S BT.  
A Fir 20" dia., bears N.34°W., 23 lks. dist., mkd. ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Cliff Stone - Oct. 1966 - C.S. File 54/31-30

-----  
Found - Orig. 16" now 16" D.Fir N.58°E., 19.8 ft. bark scribed "¼S BT" (find this dist. to be 15.8 ft.)  
Orig. 20" now 28" D.Fir N.34°W., 15.2 ft. bark scribed "¼ BT"  
Unrecorded 1" Iron pipe. (See Johnstone survey filed in 1969, M 33-49)

Set Brass cap alongside I.P. at cor., mkd:  
County Surveyor Office  
T 31 S  
R 7 W ¼ S36 | S31 R 6 W  
1966

Reblazed and rescribed:  
28" D.Fir N.34°W., 15.2 ft. mkd. ¼ S36 CS BT.  
16" D.Fir N.58°E., 19.8 ft. mkd. ¼ S31 CS BT.  
This corner lies about 450.0 ft. South and 350.0 ft. West of Pevine Creek Road and 60.0 ft. North of small draw.

Survey by Howard Johnstone - For: Roseburg Lumber Co. - Feb. 1969 - M 33-49

-----  
Found Original BTs.  
Set 1¼" x 24" Iron pipe.

Mark Smalley, L.S. #2354 - For: Kenneth Ford - July 1994 - M 120-43

-----  
Found - 1¼" IP & 1966 County BCIP (Not set)  
28" Fir, N.34°W., 15.2', stump.  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 31; and 36 of T31-7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

16" Fir, N.58°E., 14.8' (19.8) Part. healed.  
New Bts -6" Yew, N.44°E., 24.0', "¼ BT"  
30" Fir, S.58°E., 23.5', "¼ BT"  
28" Fir, S.35°E., 47.6', "¼ BT"

Douglas Co. Surveyors Office - Randall Smith, Stephen Flause-  
Aug. 4, 1994 - C.S. File 64/52-15

-----  
Found - 1¼" I.D. iron pipe leaning 8" east of plumb.  
Protrudes 5" above ground. (M33-49)

-2½" brass cap on a 1½" O.D. by 36" long iron pipe is  
found laying on top of ground near above set I.P.  
BC/IP shows no evidence of having been set. (1966)

Accessories Found -

-20" now 28" dia. 3 ft. high D.Fir stump with evidence of  
old bark scribing "¼" and partially healed single blaze  
with scribing visible "¼ S36" bears N.34°W., 15.2 ft.  
(agrees with rec.) O.B.T.

-16" now 19" dia. D.Fir with a fully healed double blaze,  
no bark scribing visible, bears N.58°E., 15.8 ft.  
(agrees with 1966 rec.) O.B.T.

-6" Yew wood with a single blaze scribed "¼ BT" bears  
N.44°E., 24.0 ft. (M120-43 agrees with rec.)

-30" D.Fir with a single blaze scribed "¼ BT" bears  
S.58°E., 23.5 ft. (M120-43 agrees with rec.)

-28" D.Fir with a single blaze scribed "¼ BT" bears  
S.38°E., 47.6 ft. (rec. S.35°E., 47.6 ft. M120-43)

Monument Set - 1¼" I.pipe is referenced and removed, measured  
24" long. 1966 DCSO BC/IP is set at referenced position,  
the marks "RESET 1994" are added to brass cap. BC/IP  
protrudes 9" above ground. 24" iron pipe is set along  
north edge of BC/IP, protrudes 7" above ground.

-Monuments are surrounded by a 24" dia. 9" high mound of  
stone.