

TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 448 survey dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8001-02)

Set a Chinkapin post, 4 ft. long, 4" sq., 24" in the ground, for the cor. to secs. 29, 30, 31 and 32 mkd. T31S R6W S29 on NE.; S32 on SE.; S31 on SW.; and S30 on NW. faces, with 5 notches on E. and 1 notch on S. edges, from which
A Fir 15" dia., bears N.66°E., 13 lks. dist. mkd. T31S R6W S29 BT.
A Fir 14" dia., bears S.70°E., 25 lks. dist. mkd. T31S R6W S32 BT.
A Fir 22" dia., bears S.6°W., 16 lks. dist. mkd. T31S R6W S31 BT.
A Fir 30" dia., bears N.53°W., 116 lks. dist. mkd. T31S R6W S30 BT.

Survey by Clifford M. Bryden - For: Roseburg Lumber Co. - Feb. 1960 - M 17-34

Set 3/4" x 18" Iron pipe from original BTs.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Cliff Stone, crew - Sept/Oct. 1966 - C.S. File 54/31-27

Found - 3/4" Iron pipe.
Orig. 15" now 34" D.Fir N.66°E., 8.6 ft. bark scribed.
Orig. 22" D.Fir now snag, S.6°W., 10.6 ft. bark scribed.
30" D.Fir, down and rotten, N.53°W., 76.6 ft.
14" D.Fir stump hole, S.70°E., 16.5 ft.

Set Brass cap alongside I.P. mkd: County Surveyors Office
T 31 S R 6 W
S 30 | S 29
S 31 | S 32
1966

New BTs -14" D.Fir S.27°E., 42.5 ft. mkd. T31S R6W S32 CS BT.
42" D.Fir S.60°W., 23.9 ft. mkd. T31S R6W S31 CS BT.
30" D.Fir North, 15.0 ft. mkd. T31S R6W S30 CS BT.

Douglas County Surveyors Office - Randall Smith & Stephen Flause - Aug. 5, 1996 - C.S. 64/69-17

Found - 2½" Brass cap on a 1½" o.d. iron pipe protruding 14" above ground.
3/4" I.D. iron pipe protruding 2" above ground is found along NW'ly edge of BC/IP .
(Cont. Next Page)

TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

22" dia. 30' high D.Fir snag with bark scribing "S BT", bears S.6°W., 11.4'.
36" dia. 2' high D.Fir stump, with bark scribing "BT" bears, N.66°E., 9.2'.
14" dia. 6' high D.Fir stump, with a gal. metal cap on top and a fully healed double blaze, bears S.27°E., 42.5'.
39" dia. D.Fir with a fully healed double blaze, bears S.60°W., 23.2'.
30" dia. down and out of position D.Fir we opened upper blaze and find scribing "30 CS" (rec north 15') evidence of cat work in area.
New BTs- 9" dia. pistol butt D.Fir, double blazed and scribed "T31S R6W S31 CS BT", bears S.24°W., 10.6' to center of root crown.

Gregg Neitsch - For: Carbon River Holdings LLC - 2/2023 - M181-76

Found - 1" I.D GIP with 2½" BC stamped "T31S R6W S30 S29 S31 S32 COUNTY SURVEYORS OFFICE 1966", 16" above ground, as shown per CS 64/69-17, from which bears:

17" D.Fir snag, no bark, S.4¾°W., 11.8' (S.6°W., 11.4' CS 64/69-17).
32" D.Fir stump, rotted, N.68¾°E., 9.2' (N.66°E., 9.2' CS 64/69-17).
14" D.Fir stump, uprooted, with healed blaze S.27°E., 42.5'.
45" D.Fir with healed blaze S.60°W., 23.6' (S.60°W., 23.2' CS 64/69-17).
21" D.Fir WITH healed blaze S.24°W., 10.6'.