

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19, 20, 29 and 30

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

Original - W.H. Byars, under contract # 448 survey dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8004-05)

 Set a Cedar post 4 ft. long, 4" sq., 24" in the ground for the cor. to secs. 19, 20, 29 and 30, mkd. T31S R6W S20 on NE.; S29 on SE.; S30 on SW.; and S19 on NW. faces, with 5 notches on E. and 2 notches on S. edges, from which
 A Fir 30" dia., bears N.45°E., 29 lks. dist. mkd. T31S R6W S20 BT.
 A Fir 36" dia., bears S.50°E., 82 lks. dist. mkd. T31S R6W S29 BT.
 A Laurel 8" dia., bears S.45°W., 38 lks. dist. mkd. T31S R6W S30 BT.
 A Fir 40" dia., bears N.82°W., 36 lks. dist. mkd. T31S R6W S19 BT.

Survey by Clifford Byrden - For: Roseburg Lumber Company - Feb. 1960 - M 17-34

 Set 4 x 4 Cedar post from original BTs.
 Scribed new BTs:
 5" Fir N.71¼°W., 39.7 ft.
 12" Fir S.11°W., 15.0 ft.
 12" Fir N.12¼°E., 20.8 ft.
 10" Fir S.62 3/4°E., 43.3 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Cliff Stone, crew - Oct. 1966 - C.S. File 54/31-32

 Found - 4 x 4 post.
 5" now 10" Fir, N.71¼°W., 39.7 ft., shows scribing.
 12" now 17" Fir S.11°W., 15.0 ft. good scar.
 12" now 17" Fir N.12¼°E., 20.8 ft., shows scribing.
 10" now 18" Fir S.62 3/4°E., 43.3 ft., shows scribing.

Set Brass cap at cor. mkd: County Surveyors Office
 T 31 S R 6 W
 S 19 | S 20
 S 30 | S 29
 1966

This corner lies approx. 60 ft. West of spring branch.

Douglas Co. Surveyors Office - Randall Smith, Stephen Flause, Aug. 26, 1996 - C.S. File 65/9-5

 Found - Tipped on side pointing SE, a 1½" O.D., iron pipe w/flanges 3 ft. below ground surface. (1966 DCSO)
 (Cont. Next Page)

TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19, 20, 29 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Found Continued -

Note: Portion of I.P. with brass cap not dug out.

Accessories Found:

40" D.Fir now remains of roots in cat road cutbank near rec. (N.82°W., 23.8 ft.) O.B.T. NE SE and SW O.B.T's now gone.

5" now 11" dia. D.Fir with a fully healed double blaze bears, N.73°W., 39.7 ft. (rec. N.71 3/4°W., 39.7 ft.) 1960.

12" now 22" dia. 1½ ft. high D.Fir stump with a fully healed lower blaze, bears S.11°W., 15.0 ft. (agrees with rec.) 1960

10" now 21" dia. 4 ft. high D.Fir stump with a fully healed double blaze bears S.62 3/4°E., 43.3 ft. (agrees with rec.) 1960

-1960 NE BT now gone.

Monument Set -

Position of flanges on found iron pipe checks well with a position determined from remaining BT's. A 2 3/8" dia. Brass cap on a 1 3/8" O.D. by 32" long iron pipe is plumb over flanges of found iron pipe. New BC/IP protrudes 5" above ground. Brass cap at cor. mkd:

Douglas County Surveyors Office

T	31	S	R
S	19	S	20
S	30	S	29
			W
			1996

New Accessories -

4" Madrone bark scribed "T31S R6W S30 CS BT" bears S.46½°W., 23.5 ft.

6" D.Fir double blazed and scribed "T31S R6W S19 CS BT" bears N.49°W., 31.2 ft.