

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 448 survey dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8002)

Set a Laurel post, 3 ft. long, 3" sq., 18" in the ground, for 1/4 sec. cor. mkd. 1/4 S on N. face, from which

A Laurel 12" dia., bears N.60°E., 23 lks. dist. mkd. 1/4 S BT.

A Laurel 12" dia., bears S.25°E., 22 lks. dist. mkd. 1/4 S BT.

Survey by Clifford M. Bryden - For: Roseburg Lumber Co. - Feb. 1960 - M 17-34

Set 3/4" x 18" Iron pipe from orig. BTs.

Scribed BTs:

17" D.Fir N.56°W., 6.5 ft.

32" Cedar S.72°E., 19.0 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Cliff Stone - Sept/Oct. 1966 - C.S. File 54/31-29

Found - 3/4" iron pipe.

Orig. 12" Laurel, now dead, N.60 1/4°E., 15.2 ft.

Orig. 12" Laurel, now 24", S.25°E., 14.5 ft. opened for scribe.

17" D.Fir now 18", N.56°W., 6.5 ft., shows good scar.

32" Cedar S.72°E., 19.0 ft. scribe visible 1/4 S BT.

Set Brass cap alongside I.P. mkd: County Surveyors Office
T 31 S R 6 W

1/4 S 29
S 32
1966

Bryden BTs all in good condition. No new trees marked.

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - John Powell, crew - May 17, 1983 - C.S. File 62/7-12

Found - 1966 County brass cap improperly marked S26/S32.

3/4" Iron pipe alongside brass cap.

Orig. 12" Madrone now 19", and uprooted with rotted out face visible on underneath side of tree, bears S.25°E., 14.5 ft. to root hole.

17" Fir, now 21" stump with good scar bears N.56°W., 6.5 ft.

32" Cedar, now 34" stump with good scar bears S.72°E., 19.0 ft.

(Cont. Next Page)

TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

I "X" out the 6 that was improperly stamped in "S26" in 1966, and stamp 9 alongside.

New Accessories:

Set spike marked "BO 1" in top of 36" Cedar stump bears N.52°E., 34.1 ft. to spike.

Set spike marked "BO 2" in top of 39" Fir stump used for tail hold in recent logging, bears S.6½°E., 40.0 ft. to spike.

Corner lies in ridge top running N.18°E., approx. 200 ft. North of road which goes to landing.