

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 448 survey dated June 13, 1882 (DCSO records Vol. 19 Page(s) 7986)

An Alder tree, 8" dia., which I mkd. T31S R6W S10 on NE.; S15 on SE.; S16 on SW.; and S9 on NW. faces, with 3 notches on E. and 4 notches on S. edges; for the cor. to secs. 9, 10, 15 and 16, from which

An Alder 8" dia., bears N.40°E., 36 lks. dist. mkd. T31S R6W S10 BT.

An Alder 8" dia., bears S.40°E., 42 lks. dist. mkd. T31S R6W S15 BT.

A Fir 14" dia., bears S.18°W., 59 lks. dist. mkd. T31S R6W S16 BT.

A Yew 6" dia., bears N.73°W., 32 lks. dist. mkd. T31S R6W S9 BT.

Douglas Co. Surveyors Office - John M. Powell and crew - 11/3/1966 - C.S. File 54/31-47

Found - 12" Yew which had been opened for scribing "3" visible. This tree however is out of the ground. All other trees not fd. Being unable to determine where Yew stood, I could not renew this corner. Tagged yew & also tagged D.Fir in creek for approx. location. Best way to reach this cor. S by walking about 1½ miles up catching creek on very old logging rd. Tagged D.Fir is very easily seen in creek

↑
See CS file for BLM opinion

↓
Douglas Co. Surveyors Office - John M. Powell and crew - Sept. 14, 1970 - C.S. File 54/31-47

Found - Orig. 12" Yew, out of the ground, with scribe "3" visible.

1" BLM Iron pipe that was agreed to be corner by BLM and C & D Lumber.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 6 W
S 9 | S 10
S 16 | S 15
1970

Set Brass cap alongside iron pipe.

New BTs -48" D.Fir S.11°E., 96.7 ft. scribed T31S R6W S15 CS BT. Continued next page

TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

5" Alder N.85°E., 10.5 ft. scribed T31S R6W S10 CSBT
36" D.Fir S.67°W., 10.0 ft. scribed T31S R6W S16 CS
BT.
18" Yew N.14°W., 59.2 ft. scribed T31S R6W S9 CS BT.
Corner lies on West side of creek at record distance.

BLM resurvey by James E. Jelley and Wayne L. Rogers, under
Group #1042, surveyed Oct. 1980/Oct. 1981 (DCSO records Vol.
45 Page(s) 17301)

The Sec. cor., perpetuated by Powell in 1970, as described in
a Douglas County Surveyor Record, monumented with an iron
post 1¼" dia., firmly set, projecting 14" above ground with
brass cap,
from which the remains of an original bearing tree:
A root hole bears N.73°W., 32 lks. dist., with down Yew
alongside 12" dia., with scribe mark 3 visible on
decayed blaze.
and the remains of bearing trees mkd. by Powell:
An Alder 9" dia., bears N.83 3/4°E., 16 lks. dist. with
healed blaze.
A Fir 51" dia., bears S.13½°E., 143 lks. dist. with
illegible scribe marks visible on partially healed
blaze.
A Fir stump 40" dia., bears S.64¼°W., 14 lks. dist. with
scribe marks T31S R6W S16 BT visible on bark.
A Yew 20" dia., bears N.16¼°W., 89 lks. dist. with scribe
marks T31S R6W S9 CS BT visible on open blaze.
and a new bearing tree:
A Fir 5" dia., bears S.55°W., 42 lks. dist. mkd. T31S R6W
S16 BT.

Fd. ok by Kris DeGroot - 8/2004 - M 146-11