

PRIMARY CORNER DESCRIPTION Cor. to Secs. 1 & 12 only

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Original - George W. Hyde under Contract #54 dated Feb. 19, 1855 (DCSO records, Vol. 19 Page 7877)

Set post from which:

- A Fir, 6" dia. bears S.18°E., 6 lks. dist.
- A Fir, 6" dia. bears N.35°E., 29 lks. dist.
- A Fir, 6" dia. bears N.20°W., 35 lks. dist.
- A Fir, 8" dia. bears S.77°W., 60 lks. dist.

Wm. P. Wright, Deputy Surveyor, under Contract #281 dated May 16, 1878, surveyed, June 27, 1878. - Resurvey of north 2 miles of the west boundary, T31S R5W. (DCSO records Vol. 33 Pg. 13666)

Search for a post or evidence of bearing trees and find none. Am certain that I am on the old line for the last 20 chains, my blazes have been on the same trees marked by former surveyor.

Set a post 6" x 6" by 5 ft. long, 20" in ground in mound of stone, from which:

- A Fir, 12" dia. bears **North** 10 lks.
- A V.Maple, 8" dia. bears N.84°W., 40 lks.
- A Fir. 14" dia. bears S.78°W., 12 lks.
- A Fir, 16" dia. bears S.4°E., 18 lks.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & C. Stone. October 3, 1966 - C.S. File 54/31-11

Found -

- 16" D.Fir, now 36", S.4°E., 11.9 ft. Had been opened & burned open more, but no scribing visible.
- 14" Fir, now down, S.78°W., 7.9 ft. Old rotten snag has axed face with faint "S" & other marks. Scribing done with very fine scribe or knife.
- 12" Fir, now down snag, **North** 6.6 ft. has old axe work, no scribe.

No trace of 8" V.Maple.

By ring count on 36" Fir it places this corner at "1878". Also call on small creek, 16.5 ft. N. of cor. hits very good.

Set - Brass Cap at corner marked: COUNTY SURVEYORS OFFICE

R	T 31	S	R
6	S1	S6	5
W	S12	S7	W
	1966		

New BTs -14" Maple, N.8°E., 31.0 ft. mkd."T31S R5W S6 CS BT"
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Cor. to Secs 1 & 12 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

12" Maple, N.58°W., 48.3 ft. mkd."T31S R6W S1 CS BT"
13" Maple, S.84°W., 36.0 ft. mkd."T31S R6W S12 CS BT"
Reblaze & rescribe: 36" D.Fir, S.4°E., 11.9 ft. mkd."T31S
R5W S7 CS BT"

Douglas Co. Surveyors Office - Larry Monrean, P.L. Earle,
F.C. Silagy. - June 28, 1978, C.S. File 60/11-24

Found -

- 1" I.P. with 1966 County Brass cap properly marked.
Monument is approx. one foot high and approx. 16½ ft.
south of a creek, course east.
- 16" Fir, now 32" bears S.1°W. (rec. S.4°E.) 13.1 ft. to
center, 12.3 ft. to face. (rec. 11.9 ft.). Tree has
partially healed double blaze "BT" visible.
- 12" Fir, now a 16" snag tipped out bears **North** 6.6 ft.
- 14" Fir stump, now dislodged bears N.78°W., 7.9 ft. to
root hole. Find old axe marks, no scribing.
- 14" Maple, now 15" bears N.8°E., 31.0 ft. to center of
scribed trunk, 31.5 ft. to center of triple forked
base. Scribed "S5" on a partially healed double blaze.
- 13" Maple now 16" bears S.85°W. (rec. S.84°W.) 36.0 ft.
Scribing visible on single blaze.

No new monument or accessories.

See C.S. File 60/24-35 for N.F. Hyde survey (1855) corner -
G. Langlitz D.C.S.O. 6/5/79

Greg Lang for Silver Butte Timber Co. Oct. 1997 - M 128-18

Set corner for Sections 1, 12 & 7

At Corner point chiseled "+" in rock. "Lang" chiseled
alongside.

New Accessories -

- Spike in face of 7" Fir bears S.37°56'E., 51.35 ft.
Scribed "T31S R5W S7" "BT"
- Spike in face of 8½" Fir bears S.63°01'W., 31,20 ft.
Scribed "T31S R6W S12" "BT"
- Spike in face of 8½" Fir bears N.68°23'E., 47.25 ft.
Scribed "T31S R5W S7" "BT"
- Spike in face of 37½" Fir bears N.26°46'W., 70.47 ft.
Scribed "T31S R6W S1" "BT"

continued next page

PRIMARY CORNER DESCRIPTION Cor. to Secs. 1 & 12 only

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

BLM dependent resurvey by Daniel E. Weller, Cadastral Surveyor, under Group #1884, surveyed July/Sept 1998. (DCSO records Vol. 53 Page(s) 20474-5)

The cor. of secs. 1 & 12 only, T31S R6W, determined at proportionate measurement by Lang, in 1998. There is no remaining evidence of the original corner, therefore, this position is accepted as the corner; monumented with an X chiseled into side of exposed rock outcrop, with a steel fence post alongside, from which bearing trees mkd. by Lang:

A fir, 9" dia., bears N.68 3/4°E., 72½ lks., with scribe marks S7 T31S R5W BT visible on partially healed double blaze.

A fir, 7" dia., bears S.38¼°E., 78½ lks., with scribe marks S7 T31S R5W BT visible on partially healed double blaze.

A fir, 9" dia., bears S.63 3/4°W., 47½ lks., with scribe marks S12 T31S R6W BT visible on partially healed double blaze.

A fir, 38" dia., bears N.26 3/4°W., 108 lks., with scribe marks S1 T31S R6W BT visible on partially healed blaze.

At the corner point

Set a brass tablet, 3¼" dia., 3½" stem, cemented in drill hole, with top mkd.

```

      T 31 S
    R 6 W   R 5 W
     S 1   |   S 7
     S 12  |
           1998

```

Fd. BLM BC in solid rock & 4 BTs/healed blaze D. Edwards, 2/2009 - M158-67