

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 100240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 30; & 25 of T31-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8030)

Set a Fir post 40" long, 3" sq., 24" in the ground, marked ¼ S on W. side for the ¼ sec. cor., from which
A Fir 26" dia., bears S.85°E., 46 lks. dist. mkd. ¼ S BT.
A Fir 36" dia., bears S.25°W., 46 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Cliff Stone, crew - Dec. 1966 - C.S. File 54/36-6

Found - 36" now 48" D.Fir S.25°W., 30.4 ft., bark scribed, faint.
26" now 32" D.Fir S.85°E., 30.4 ft., shows old face, opened for scribe "1 S". (Find this bearing and distance to be S.89°E., 26.4 ft.)

Set Brass cap at cor. mkd: County Surveyors Office
T 31 S
R8W ¼ S25|S30 R7W
1966

New BTs -13" D.Fir N.55½°W., 26.0 ft. mkd. ¼ S25 CS BT.
10" D.Fir S.63°E., 36.5 ft. mkd. ¼ S30 CS BT.

Mark Smalley - For: Roseburg Resources - 1/2002 - C.S. File 65/42-41 & M 139-70

Found - 1966 DCSO IPBC, (properly marked)
1882, 48" Fir, S.25°W., 30.4 good healed.
1882, 32" Fir stump, S.89°E., 26.4 stump.
1966, 19" Fir N.55½°W., 26.0 good healed.
1966, 10" Fir S.63°E., 36.5 gone.
New - 2001, 9" Fir N.86°E., 21.8 "¼ S BT"
2001, 16" Fir N.49°E., 32.9 "¼ S BT"