

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 100600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 6 & 7; 1 & 12, T31-8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8033-34)

-----  
Set a Fir post 4 ft. long, 4" sq., 2 ft. in the ground, marked T31S R7W S6 on NE. face; S7 on SE. face; S12 on SW. face and R8W S1 on NW. face; Also five notches on the South and one notch on the North angles of same for the cor. to secs. 1, 6, 7 and 12, from which

- A Fir 24" dia., bears N.36°E., 65 lks. dist. mkd. T31S R7W S6 BT.
- A Fir 8" dia., bears S.22°E., 50 lks. dist. mkd. T31S R7W S7 BT.
- A Fir 12" dia., bears S.50°W., 21 lks. dist. mkd. T31S R8W S12 BT.
- A Fir 12" dia., bears N.22°W., 27 lks. dist. mkd. T31S R8W S1 BT.

GLO survey by Gerald A. Sorrels, U.S. Surveyor, under under Special Instructions dated March 1, 1917 - (DCSO records Vol. 19 Page(s) 8083) and (duplicated info. in Vol. 27 Pg. 11631)

-----  
At the sec. cor., the point for which is located by reference to the bearing trees, the NE. tree having fallen. At the exact cor. point

Set an iron post 3 ft. long, 2" dia., 24" in the ground, for cor. to secs. 1, 6, 7 and 12, with brass cap marked:

T31S	
R8W	R7W
S1	S6
S12	S7
1918	

from which

- A Fir 8" dia., bears N.85°E., 43 lks. dist. mkd. T31S R7W S6 BT. (New BT)
- A Fir 10" dia., bears S.20°E., 50 lks. dist. mkd. T31S R7W S7 BT. (Old BT)
- A Fir 14" dia., bears S.46°W., 21 lks. dist. mkd. T31S R8W S12 BT. (Old BT)
- A Fir 16" dia., bears N.19°W., 26 lks. dist. mkd. T31S R8W S1 BT. (Old BT)

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & W. Penley, crew - June 1968 - C.S. File 54/36-82

-----  
Found - 1918 GLO brass cap, properly marked.  
10" now 14" D.Fir S.20°E., 33.0 ft. shows good scar.  
(Cont. Next Page)

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 100600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 6 & 7; 1 & 12, T31-8

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

14" now 17" D.Fir S.46°W., 13.9 ft., shows good scar  
16" now 25" D.Fir N.19°W., 17.2 ft. shows good scar.  
No trace of NE. BT.  
New BT - 16" D.Fir N.3°E., 22.3 ft. mkd. "T31S R7W SC CS BT."  
All other trees OK and tagged.

David Edwards - For: Seneca Jones Timber & Roseburg Resources  
- Nov. 2017 - M173-76  
-----  
Found - 1918 GLO Brass cap  
All previous BTs are either burned away or severely  
burned and dead.  
No live trees available due to fire.  
Set - 6' steel posts 2 ft north, 2 ft east, 2 ft. south  
and 2 ft. S.88°W.