

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 140300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8075)

Set a Cedar post 4 ft. long, 4" sq., 18" in the ground mkd. 1/4 S. on N. side for the 1/4 sec. cor., from which

A Laurel 7" dia., bears S.34°E., 15 lks. dist. mkd. 1/4 S BT.

A Fir 30" dia., bears N.25°W., 20 lks. dist. mkd. 1/4 S BT.

Douglas County Surveyors Office - James W. Byron, Surveyor
Frank Jones, crew - C.S. File 54/36-32 - 1969

Corner searched for, not found.
Found possible NW BT. The possible BT matches calls and ridge line crossing, but tree is badly burnt. We found possible notch, but no way to renew it. No scribing.

Mark Smalley - For: Roseburg Resources -1/2002 - M 139-70

Set - An aluminum cap on a 5/8"x48" iron rod marked "LS 2354 2002"

9" Fir N.84°E. 49.6' "1/4 S BT"

10" Fir S.88°E. 41.2' "1/4 S BT"

6' Fir S.36°W. 18.1' "1/4 S BT"

11" Fir N.80°W 17.7 "1/4 S BT"

Ron Quimby - Crew: J. Leonard and N. Fromdahl - 2/2014 - C.S.
File 65/82-23

Condition report only
Found - 5/8" I.Rod with alum. cap (properly mkd)
14" D.Fir N.84°E., 49.6 ft. good scar.
16" D.Fir S.33°E., 41.2 ft. good scar.
12" D.Fir S.36°W., 18.1 ft. good scar.
16" D.Fir N.80°W., 17.7 ft. good scar.
Compass decl. 15½°E.