

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19, 20, 29 and 30

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8073)

-----  
Set a Fir post 4 ft. long, 4" sq., 20" in the ground mkd. T31S R7W S20 on NE.; S29 on the SE.; S30 on the SW.; and S19 on NW. faces; of same. Also, 2 notches on the S. and 5 notches on E. angles of the same for the cor. to secs. 19, 20, 29 and 30, from which

- A Fir 12" dia., bears N.53°E., 58 lks. mkd. T31S R7W S20 BT.
- A Fir 15" dia., bears S.78°E., 50 lks. dist. mkd. T31S R7W S29 BT.
- A Laurel 12" dia., bears S.8°W., 25 lks. dist. mkd. T31S R7W S30 BT.
- A Fir 22" dia., bears N.14°W., 70 lks. dist. mkd. T31S R7W S19 BT.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #531 - Surveyed Oct 1963/June 1964 - (DCSO records Vol. 33 Page(s) 13643-44)

-----  
The Sec. cor., determined from the original bearing trees:  
A Fir 21" dia., bears N.56°E., 58 lks. dist., with scribe marks W BT visible on bark blaze. (Rec. brg. N.53°E.)  
A Fir 25" dia., bears S.76½°E., 50 lks. dist., with scribe marks T S BT visible on bark blaze. (Rec. brg. S.78°W.)  
A Madrone snag 17" dia., bears S.8°W., 41 lks. dist. with illegible scribe marks visible on rotted blaze. (Rec. dist. 25 lks.)  
A Fir 35" dia., bears N.8°W., 70 lks. dist., with illegible scribe marks visible. (Rec. brg. N.14°W.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 21" in the ground, with brass cap mkd:

T 31 S R 7 W  
S 19 | S 20  
S 30 | S 29  
1963

from which new bearing trees:

- A Fir 10" dia., bears S.82½°W., 44 lks. dist. mkd. T31S R7W S30 BT.
- A Fir 7" dia., bears N.19½°W., 27 lks. dist. mkd. T31S R7W S19 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & W. Penley, crew - March 19, 1970 - C.S. File 54/36-31

-----  
Found - 1963 BLM brass cap, properly marked.  
(Cont. Next Page)

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19, 20, 29 and 30

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

10" now 11" D.Fir S.82½°W., 29.0 ft., shows good scar.  
7" now 8" D.Fir N.19½°W., 17.8 ft., shows good scar.  
Orig. 21" now 24" D.Fir N.56°E., 38.3 ft., very faint bark scribing.  
Orig. 25" now 27" D.Fir S.76½°E., 33.0 ft., very faint bark scribing.  
Reblazed and rescribed:  
24" D.Fir N.56°E., 38.3 ft. mkd. "T31S R7W S20 CSBT"  
27" D.Fir S.76½°E., 33.0 ft. mkd. "T31S R7W S29 CSBT"  
This corner lies westerly slope approx. 140.0 ft. East of creek.

Mark Smalley - For: Roseburg Resources -1/2002 - M 139-70  
-----  
Found - 1963 cadastral brass cap on an iron pipe  
9" Fir N.19½°W. 17.8' snag top healed face.  
26" Fir S.76½°E. 33.0' healed (OBT)  
23" Fir stump N.56°E. 38.3' (OBT)  
Scribed- 7" Fir S.37°W. 17.7' "S 30 BT"  
9" Fir S.89°E. 8.7' "S 29 BT"

Ron Quimby - Crew: J. Leonard and N. Fromdahl - 2/2014 - C.S.  
File 65/82-24  
-----  
Condition Report only  
Found - Brass cap, (properly marked)  
24" D.Fir stump N.56°E., 38.3' good scar.  
12" D.Fir S.89°E., 8.7 ft. good scar.  
27" D.Fir S.76°E., 33.0 ft. good scar.  
8" D.Fir S.37°W., 17.2 ft. good scar.  
10" D.Fir (snag top) N.19°W., 17.8 ft. good scar.  
Compass decl. 15½°E.