

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 400400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 15, 16, 21 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8058)

Set a Cedar post 4 ft. long, 4" sq., 24" in the ground marked T31S R7W S15 on NE. face; S22 on SE. face; S21 on the SW. face; and S16 on NW. face, also 3 notches on the S. and E. angles of same for the cor. to secs. 15, 16, 21 and 22, from which

- A Fir 14" dia., bears N.18°E., 49 lks mkd. T31S R7W S15 BT
- A Fir 40" dia., bears S.69°E., 22 lks mkd. T31S R7W S22 BT
- A Cedar 24" dia. bears S.58°W., 48 lks mkd T31S R7W S21 BT
- A Fir 12" dia., bears N.25°W., 9 lks. mkd. T31S R7W S16 BT

Douglas Co Surveyors Office - James Byron, Deputy - John Powell & Wm Stoffel, crew - Oct. 31, 1962 - C.S. 49/109-10

Found all orig. bearing trees, all check record.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 7 W
S 16 | S 15
S 21 | S 22
1962

New BT - 5" Fir bears East, 3.8 ft. scribed S22 CS BT.

Fd. and used in BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #531 - Surveyed Oct 1963/June 1964 - (DCSO records Vol. 33 Page(s) 13635)

Fd. and used in BLM resurvey by Owen C. Chatters II, Cadastral Surveyor, under Group #834, surveyed April/June 1974 - (DCSO records Vol. 39 Page(s) 15740)

Ron Quimby - Crew: R. Olsen & J. Leonard - 10/2017 - C.S. File 65/99-27

Found - DCSO 2½" brass cap on 1" I. Pipe (properly mkd)

- 48" Fir stump S.69°E., 14.5 ft.
- 12" Fir stump N.25°W., 6.0 ft.
- 46" cedar stump S.58°W., 31.7 ft.
- 10" Fir stump N.18°E., 32.3

- New - 6" Fir S.24°E., 8.3 ft. scribed T31S R7W S22 BT.
- 8" Fir S.35°W., 23.3 ft. scribed T31S R7W S21 BT.
- 8" Fir N.45°E., 20.6 ft. scribed T31S R7W S15 BT.
- 8" Fir N.41°W., 20.3 ft. scribed T31S R7W S16 BT.

Note - Area badly burnt 9/2017
Compass decl. 15½°E.