

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8061)

Marked a Fir tree, 28" dia., bears $\frac{1}{4}$ S. on W. side for the $\frac{1}{4}$ sec. cor., from which

A Fir 24" dia., bears N.85°W., 55 lks. dist. mkd. $\frac{1}{4}$ S BT.

A W.Oak 16" dia., bears S.78°E., 52 lks. dist. mkd. $\frac{1}{4}$ S BT

Douglas Co. Surveyors Office - John M. Powell, J. Heritage & W. Penley, crew - Jan. 4, 1971 - C.S. File 54/36-30

Found - 28" now 40" D.Fir corner tree, faint but good bark scribe, " $\frac{1}{4}$ S BT" scribe on SW. side of tree.

24" now 40" D.Fir N.85°W., 36.3 ft., no bark scribe found, opened tree. No burl or evidence of face.

16" now 18" W.Oak S.78°E., 34.3 ft. tree rotted out, old axe work or evidence of.

Call to creek South, 165.0 ft., hits good.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 7 W

$\frac{1}{4}$

S 9 | S 10

1971

Set under and on West side of corner tree.

Reblazed and rescribed:

40" D.Fir N.85°W., 36.3 ft. scribed " $\frac{1}{4}$ S9 CS BT".

New BT - 12" D.Fir N.2°E., 30.6 ft. scribed " $\frac{1}{4}$ S10 CS BT".

BLM resurvey by Owen C. Chatters II, Cadastral Surveyor, under Group #834, surveyed April/June 1974 - (DCSO records Vol. 39 Page(s) 15743)

The $\frac{1}{4}$ sec. cor., monumented with the original corner tree, a Fir 52" dia., with healed blaze on W. side. This tree was remarked $\frac{1}{4}$ S9|S10 on bark blaze, in 1971 by the DCSO. Alongside the corner tree is an iron post, 2" dia., firmly set, projecting 10" above ground with brass cap mkd. per record, from which the original bearing trees:

An Oak 18" dia., bears S.78°E., 52 lks with decayed blaze.

A Fir 40" dia., bears N.85°W., 55 lks., with healed blaze. and a bearing tree mkd. by the County:

A Fir 14" dia., bears N.2°E., 46 $\frac{1}{2}$ lks., with healed blaze. from which

An Iron post 28" long, 2 $\frac{1}{2}$ " dia., set 24" in the ground, for a reference monument, bears N.75°E., 50 lks. dist., with brass cap mkd. T31S R7W S10 RM 1974 and an arrow pointing to the corner.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>An Iron post 28" long, 2½" dia., set 24" in the ground, for a reference monument, bears S.75°W., 50 lks. dist., with brass cap mkd. T31S R7W S9 RM 1974 and an arrow pointing to the corner.</p>
<p>Cor. Fd. and used in BLM resurvey by Wayne L. Rogers, Cadastral Surveyor, Group #834, surveyed July 1979 - (DCSO records Vol. 42 Page(s) 16554-55)</p>
<p>Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Randy Smith, crew - Feb. 14, 1983 - C.S. File 62/7-13 ----- CONDITION REPORT ONLY Found - Original corner tree, a 52" Fir with well healed blaze on West side & "¼ S9 S10" bark scribed on SW side. 1½" iron pipe with brass cap attached firmly set, partially under West side of corner tree. Cap mkd "County Surveyors Office T31S R7W ¼ S9 S10 1971". From Corner tree: Orig. 16" Oak now 18" with rotted hole in the area a blaze would have been located, bears S.88°E., 30.2 ft. (Rec. S.78°E., 34.3 ft.) Orig. 24" Fir now 41" with scribed "¼ S" visible in previously opened blaze, bears N.88°W., 32.6 ft. (Rec. N.85°W., 36.3 ft.) 12" Fir, now 12" with well healed double blaze, bears N.2°E., 30.3 ft. (Rec. 30.6 ft.) 2½" Iron pipe with brass cap attached marked "T31S R7W S9 RM 1974 33 ft. (Rec. says S10) and an arrow pointing to the corner, bears <u>N.75°W., 29.2 ft.</u> (Rec. <u>N.75°E. 33 ft.</u>) ----- 2½" Iron pipe with brass cap attached mkd "T31S R7W S9 RM 1974 33 ft." & an arrow pointing to the corner bears S.75°W., <u>29.0 ft.</u> (Rec. 33.0 ft.)</p>
<p>Ron Quimby - Crew: N. Fromdahl & R. Heichel - 12/2017 - C.S. File 65/99-38 ----- Found - 52" orig. Corner tree remnant burnt stump. 2½" DCSO brass cap alongside burnt stump (properly mkd) 2½" brass cap (bent) N.75°W., 28.7 (Rec. 29.2) New - PK & chiseled X in 8' vert rock face S.58°E. 18.3 ft 10" Fir S.45°W., 33.8 ft. scribed ¼ S9 BT. 12" Fir N.45°W., 34.7 ft. scribed ¼ S9 BT. Note - Corner is approx 165' North of small Creek flow NW. Area badly burnt 9/2017 Compass decl. 15½°E.</p>