

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8061)

Marked Laurel tree, 24" dia., on N. side, 1/4 S. for 1/4 sec. cor., from which

A Fir 40" dia., bears s.45°W., 8 lks. dist. mkd. 1/4 S BT

A Fir 22" dia., bears N.22°W., 60 lks. dist. mkd. 1/4 S BT

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & W. Penley, crew - March 18, 1970 - C.S. File 54/36-15

Found - 40" now 60" D.Fir, S.45°W., 5.3 ft., bark scribe visible "1/4 S BT".

No trace of NW. bearing tree nor corner tree. There has been a fire through area.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 7 W

1/4 S 10

S 15

1970

New BT - 38" D.Fir N.59°W., 6.8 ft. scribed "1/4 S10 CS BT"

Reblazed and rescribed:

60" D.Fir S.45°W., 6.4 ft. scribed "1/4 S15 CS BT".

(New distance to center of tree)

Cor. Fd. and used in BLM resurvey by Owen C. Chatters II, Cadastral Surveyor, under Group #834, surveyed April/June 1974 - (DCSO records Vol. 39 Page(s) 15742)

Ron Quimby - Crew: R. Olsen & R. Heichel - C.S. File 65/99-39

Found - 2 1/2" DCSO brass cap (properly mkd)

50" Fir N.59°W., 6.8 ft. good scar.

66" Fir S.45°W., 6.4 ft. good scar.

New - 8" Fir N.49°E., 20.2 ft. scribed 1/4 S10 BT.

5/8" I. Rod with plastic cap ie engineering S.30°E., 24.0 ft. with post alongside.

Note - Area badly burnt 9/2017

Compass decl. 15 1/2°E