

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8048)

Set Pine post 3 ft. long, 3" sq., 18" in the ground for 1/4 sec. cor. marked 1/4 S. on W. face, from which
A Pine 26" dia., bears S.12°W., 28 lks. dist. mkd. 1/4 S BT.
A Pine 12" dia., bears N.18°E., 62 lks. dist. mkd. 1/4 S BT.

Survey by Howard W. Johnstone - For: Roseburg Lumber Co. - Aug/Sept. 1962 - C.S. File 51/163-11

Found - 14" Pine S.18°E., 40.9 ft., snag.
26" Pine S.12°W., 18.5 ft., stump hole.
Set 1" x 30" Iron pipe.
Scribed -24" D.Fir N.2 1/2°W., 21.0 ft.
6" Pine S.42°E., 5.6 ft.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #531 - Surveyed Oct 1963/June 1964 - (DCSO records Vol. 33 Page(s) 13627)

The 1/4 sec. cor., recorded and remonumented in 1962 by Johnstone, with an iron pipe, 1" dia., 10" above ground, firmly set, from which the remains of the original bearing trees:

A Pine snag 12" dia., bears N.18°E., 62 lks. dist. mkd. 1/4 S BT on opened double blaze.
A stump hole bears S.12°W., 32 lks. dist. (Rec. dist. 28 lks.)

and bearing trees mkd. by Johnstone:

A Pine 8" dia, bears S.43 3/4°E., 9 lks. dist. mkd. with a partially healed double blaze.
A Fir 25" dia., bears N.4 1/2°W., 32 lks. dist. mkd. with a partially healed double blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 23" in the ground, with brass cap mkd:

T 31 S R 7 W

1/4
S 27 | S 26

1964

Reset the iron pipe alongside the iron post.

Survey by Howard W. Johnstone, L.S. #498 - For: Roseburg Resources Co. - May 19, 1989 - C.S. File 63/95-1

Found - 26" D.Fir N.2 1/2°W., 21.0 ft., healed face, good condition.

(Cont. Next Page)

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

No evidence of any other BTs of record.
Brass cap and I.P. had been dug out during fire trail construction.
Reset the I.P. and B.C. in their proper location from the remaining D.Fir BT.
New BT - 8" Chinquapin S.10°W., 38.4 ft. scribed "¼ S27 BT"
No trees available to scribe in sec. 26 as it has been recently clear cut.

Douglas Co. Surveyors Office - Randall Smith, Stephen Flause, Sept. 5, 1996 - C.S. File 65/9-9

Found - 3¼" dia. brass cap on a 2½" O.D. iron pipe protrudes 12" above ground (1964 BLM)
- 1" I.D. iron pipe, protrudes 14" above ground, found along west edge of BC/IP. (1962)
- Above monuments reset by Howard Johnstone in 1989.

Accessories Found -
26" dia. Pine now root hole, bears S.12°W., 21.1 ft. (agrees with 1964 BLM rec.) O.B.T.
- Orig. NE BT now gone.
24" now 33" dia. D.Fir with a fully healed double blaze, bears N.2½°W., 21.0 ft. (agrees with rec.) 1962 Johnstone.
- 1962 Johnstone SE BT now gone.
8" now 9" dia. Chinquapin with an open double blaze, scribing visible "¼ S27 BT" bears S.10°W., 38.4 ft. (agrees with rec.) 1989 Johnstone.

New Accessories -
11" dia. D.Fir, double blazed and scribed "¼ S27 CS BT" bears West, 17.5 ft.
24" dia. 1 ft. high D.Fir stump, set an 8" boat spike through a BT tag on top near center. Top of boat spike stamped "B0 1". Boat spike bears N.61½°E., 18.7 ft.