

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 2; & 35 of T30-7

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 17 Page(s) 7229)

 Set ¼ sec. post, from which
 A W.Pine, 30" dia., bears N.38°E., 26 lks. dist.
 A S.Pine, 48" dia., bears S.72°E., 80 lks. dist.

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #'s 350 and 680 - Surveyed April/Sept. 1969 - (DCSO records Vol. 35 Page(s) 14500-01)

 Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
 Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 30 S
 S 35
 ¼ S 2
 T 31 S R 7 W
 1969

from which
 A Fir 43" dia., bears N.14°W., 136 lks. dist. mkd. ¼ S35 BT.
 A Fir 20" dia., bears S.2¼°W., 108 lks. dist. mkd. ¼ S2 BT

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #680, surveyed June 1977 - (DCSO records Vol. 41 Page(s) 16260)

 Point for the ¼ sec. cor. of secs. 2 and 35, at proportionate distance; there is no remaining evidence of the original corner.

From this point, the ¼ sec. cor. erroneously reestablished by Jelley, in 1969, bears N.48°01'E., 0.04 chs. dist., set, mkd. and witnessed as described in the official record.

I remove the iron post, destroy the marks on the bearing trees, and at the proportionate corner point
 Reset the iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

T 30 S
 S 35
 ¼ S 2
 T 31 S R 7 W
 1977
 1969

from which
 A Fir 5" dia., bears N.12½°E., 65 lks. dist. mkd. ¼ S35 BT
 A Fir 8" dia., bears S.34½°W., 88 lks. dist. mkd. ¼ S2 BT.