

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by W.H. Byars, Deputy Surveyor under contract # 456 dated July 28, 1882 (DCSO records Vol. 19 Page(s) 8104)</p> <p>-----</p> <p>Set a Fir post 3 ft. long, 3" sq., 20" in the ground mkd. ¼ S on the W. side for the ¼ sec. cor., from which</p> <p>    A Fir 24" dia., bears S.30°W., 5 lks. dist. mkd. ¼ S BT.</p> <p>    A Fir 12" dia., bears N.42°E., 16 lks. dist. mkd. ¼ S BT.</p>
<p>GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page 8239)</p> <p>-----</p> <p>Post gone, witness trees standing and agree with notes furnished by the Surveyor General.</p> <p>Set a Fir post, 4 ft. long, 4" sq., 24" in the ground at the point established from the witness trees for the ¼ sec. cor. post mkd. Sec.30 on E. and S25 ¼ S on W. faces.</p>
<p>BLM Resurvey by C. Albert White, Harold D. Corbing Cadastral Surveyor and Donald R. Beck, Surveying Technician, Under Group #446, Surveyed Nov. 1960/Sept. 1962 - (DCSO records Vol. 31 Page(s) 13182-83)</p> <p>-----</p> <p>The ¼ sec. cor., perpetuated with an iron pipe, 1" dia., firmly set, protruding 4" above the ground, from which the original bearing trees:</p> <p>    A Fir 22" dia., bears N.80°E., 40 lks. mkd. with healed blaze and cruiser marks (Rec. N.42°E., 16 lks. dist.)</p> <p>    A Fir 33" dia., bears S.30°W., 5 lks. dist., to face, mkd. ¼ on old bark blaze. Remarkd ¼ S25 BT.</p> <p>At the corner point</p> <p>Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:</p> <p style="text-align: center;">¼ S 25   S 30 R 9 W   R 8 W T 31 S 1962</p> <p>Deposit local cor. monument alongside iron post.</p>
<p>David Edwards - For: URAM Forests LLC - April 2004 - M144-32</p> <p>-----</p> <p>Found - BLM brass cap           36" Fir S.30°W., 3.3' w/healed blaze.</p> <p>New BT - 7" Fir S.68°E., 22.47' scribed "¼S 30 BT"</p>
<p>DCSO-GIS Corner visitation - 1/23/2004 - Typed: 2/10/2011 - C.S. File 67/33-1</p> <p>-----</p> <p>Monument - 2½" IP/BC                      Comment - needs rehab</p>