

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 100440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 18; & 13, T31-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 456 dated July 28, 1882 (DCSO records Vol. 19 Page(s) 8106)

Set a Cedar post 3 ft. long, 3" sq., 20" in the ground, mkd. 1/4 S on the W. side for the 1/4 sec. cor., and from which
A Fir 24" dia., bears N.64°E., 18 lks. dist. mkd. 1/4 S BT
A Fir 22" dia., bears S.43°W., 14 lks. dist. mkd. 1/4 S BT

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page 8241)

Corner post gone. Set a Fir post, 4 ft. long, 4" sq., 24" in the ground, mkd. 1/4 S on E. and S13 1/4 S on W. faces. Established from old witness corners.

BLM Resurvey by C.A. White, H.D. Corbing Cad. Surveyor & D.R. Beck, Surveying Tech, Under Group #446, Surveyed Nov. 1960/Sept. 1962 - (DCSO recs Vol. 31 Pages 13185-86)

The 1/4 sec. cor., determined at record distance from the original bearing trees:

A Fir 37" dia., bears N.53 3/4°E., 18 lks. dist., mkd. 1/4 S BT on bark blaze, remarked 1/4 S18 BT on bark blaze. (Rec. brg. N.64°E.)

A Fir 31" dia., bears S.48 3/4°W., 14 lks. dist., visible scribe marks on bark blaze, remarked 1/4 S13 BT. (Rec. brg. S.43°W.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

1/4

S 13 | S 18
R 9 W | R 8 W
T 31 S
1962

Douglas Co. Surveyors Office - John M. Powell, and crew - March 17, 1967 - C.S. File 54/32-43

Found - GLO brass cap mkd. in 1962.

37" D.Fir, now broken snag, N.53 3/4°E., 11.9 ft., bark scribed 1/4 S18 BT.

31" D.Fir, now stump, S.48 3/4°W., 9.2 ft. Stump out of ground, scribe visible S13.

New BTs- 14" D.Fir N.77°E., 18.8 ft. mkd. 1/4 S18 CS BT.

6" Live Oak S.14°W., 56.6 ft. mkd. 1/4 S13 CS BT.

Corner lies East of Elk Valley Road approx. 150 ft.

cont.

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 100440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 18; & 13, T31-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Fd. BC & BTs by C. Woodruff, 4/2008 - M156-5 Fd. by C. Woodruff, 6/2010 - M161-7</p>
<p>Ron Quimby - Crew: N. Fromdahl & R. Olsen - 2/2015 - C.S. File 65/87-14</p> <p>-----</p> <p>Found - BLM brass cap 35" Fir snag, N.50°E., 12.0 ft. (rotted) 26" Fir N.77°E., 18.8 ft. good scar.</p> <p>New - 12" Fir N.35°W., 15.8 ft. scribed ¼ S13 BT. 6" Fir S.36°W., 24.5 ft. scribed ¼ S13 BT. 16" Fir S.15°W., 37.2 ft. scribed ¼ S13 BT. Clear cut unit to the east.</p> <p>Note - Corner is on west of new clear cut unit approx 200' east of Rd. #31-8-31 and approx. 200' north of logging spur to clear cut. Rd. #9-13</p>
<p>Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 2-10-25 - C.S. File 67/60-4</p> <p>-----</p> <p>Found - BLM brass cap projecting 4" 30"x10ft very rotted fir snag N.50°E. 12.0ft. No blaze, no nail. 26"x11ft sawn fir N.77°E. 18.8ft. Fully healed single blaze. 17" Fir N.35°W. 15.9ft (rec 15.8ft) fully healed single blaze. 10" Fir S.36°W. 24.3ft (rec 24.5ft) fully healed single blaze. 23" Fir S.15°W. 37.2ft fully healed single blaze. Metal posts 1½ft south and on north edge of B.C. All trees were side spiked with 3½" mag nails right side center.</p> <p>Notes - Mon is approx 200' E. of gravel road on moderate W., slope. Young reprod to E., older forest W.</p> <p>Compass decl. 14½°E. OCRS COORDINATE SYSTEM COTTAGE GROVE-CANYONVILLE ZONE N 42.87508 W 123.70199</p>