

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 31 & 32; 5 & 6, T32-8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 456 dated July 28, 1882 (DCSO records Vol. 19 Page(s) 8101)

-----  
Set a stone 16x14x10", 8" in the ground mkd. with 5 notches on the E & 1 notch on the W for the cor. to secs. 5, 6, 31 & 32, & from which

A Live Oak 5" dia., bears N.30°E., 44 lks. mkd. T31S R8W S32 BT.

A Fir 28" dia., bears S.70°E., 42 lks. mkd. T32S R8W S5 BT

A Fir 20" dia., bears S.25°W., 56 lks. mkd. T32S R8W S6 BT

A Fir 10" dia. bears N.78°W., 38 lks. mkd. T31S R8W S31 BT

Milner L. Larson - July 1956 - C.S. File 42/167 and M 3-3

-----  
Original corner could not be found after intensive search, so corner set by proportionate measurement.

Set 1/2" iron pipe for corner.

Scribed four BTs:

5" Tan Oak N.59°30'E., 6.3 ft.

12" Tan Oak S.10°00'E., 11.1 ft.

6" Tan Oak S.29°00'W., 28.6 ft.

6" Tan Oak N.81°30'W., 21.8 ft.

Douglas Co. Surveyors Office - John M. Powell, and crew - Jan. 1967 - C.S. File 54/36-77

-----  
Found - No trace of original corner.

5/8" Iron rod at corner (not 1/2" I.P.)

12" now 13" Tan Oak S.10°E., 11.1 ft. scribed 3642 BT.

6" now 7" Tan Oak, S.29°W., 28.6 ft. scribed 3642 BT

6" now 7" Tan Oak N.81½°W., 21.8 ft. scribed 3642 BT

5" Tan Oak, now down, N.59½°E., 6.3 ft.

New BTs- 8" Tan Oak N.7°E., 30.3 ft. mkd. T31S R8W S32 CSBT.

20" D.Fir S.4½°E., 17.7 ft. mkd. T32S R8W S5 CS BT.

Corner lies on steep, East slope and about 300 ft. W. of Hayes Creek.

BLM dependent resurvey by Terrence O. Nickerson, Cadastral Surveyor under Group #2004, survey March/Oct. 2002- (DCSO records Vol. 54 Page(s) 21084)

-----  
The cor. of secs. 5, 6, 31, & 32, reestablished at proportionate measurement & recorded by Larson in 1956. There is no remaining evidence of the orig. cor., therefore this point is accepted as the corner; monumented with an iron rod, 5/8" dia., firmly set, projecting 10" above the ground, from which BTs mkd. by Larson continued next page

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 31 & 32; 5 & 6, T32-8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A tan oak, 24" dia., bears S.10°E., 11.1 ft., with healed double blaze.

A tan oak, 18" dia., bears S.29°W., 28.6 ft., with healed double blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 26" in the ground, directly over the iron rod, with brass cap mkd.

T 31 S R 8 W

S 31 | S 32

S 6 | S 5

T 32 S

2002

Deposit a magnet in a white plastic case at the base of the stainless steel post.

No suitable bearing trees available in the NE. or NW. quadrants.

Fd. as per 2002 BLM resurvey by D. Edwards, 3/2011 - M162-26