

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 31 & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 19 Page(s) 8150)

Set a stone 12x10x8", 8" in the ground, marked ¼ S on the W side for the ¼ sec. cor., and from which
 A fir, 12" dia., bears N.80°W., 25 lks., mkd: ¼ S BT.
 A Live Oak, 5" dia., bears N.40°E., 14 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Frank Jones & C. Stone - Jan. 1967 (1966?) - C.S. File 54/36-55

Found - No trace of Corner Stone Monument nor NE. BT, Orig. 12" Fir N.80°W. 16.5 ft., now down, scribe "¼S", previously opened.
Set - Brass Cap at Cor. mkd: County Surveyors T31S R8W Office, 1967 ¼ S 31|S 32
New BTs- 14" D.Fir N.42°W. 29.5 ft. mkd. ¼ S31 CS BT.
 19" D.Fir N.57°E. 7.2 ft. mkd. ¼ S32 CS BT.
Note - This corner lies approx. 100 ft. E. of Hayes Creek, on steep, west slope.

BLM dependent resurvey by Terrence O. Nickerson, Cadastral Surveyor under Group #2004, survey March/Oct. 2002- (DCSO records Vol. 54 Page(s) 21086-7)

The ¼ sec. cor. of secs. 31 & 32, perpetuated and recorded by the Douglas County Surveyors Office in 1967, monumented with an iron post, 1" dia., firmly set, projecting 16" above the ground, with brass cap (properly) mkd.
from which the remains of an original bearing tree
 A root hole, bears N.80°W., 16.5 ft., alongside of which is lying an uprooted fir, size indeterminate, with no marks visible on partially healed blaze.
and bearing trees mkd. by the Douglas County Surveyor
 A fir, 25" dia., bears N.57°E., 7.2 ft., with healed blaze
 A fir, 24" dia., bears N.42°W., 28.4 ft. with healed blaze