

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 200500

PRIMARY CORNER DESCRIPTION Cor Secs 7, 8, 17, & 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 19 Page(s) 8159)

Set a cedar post 4 ft. long, 4" sq., 20" in the ground, mkd: T31S R8W S8 on NE, S17 on SE, S18 on SW, and S7 on NW faces. Also 5 notches on the East and 4 notches on the South angles of same for the cor. to secs. 7, 8, 17, & 18, from which

- A fir, 14" dia. bears N.41°E., 30 lks. mkd: T31S R8W S8 BT
- A Fir, 12" dia. bears S.43°E. 25 lks. mkd: T31S R8W S17 BT
- A fir, 11" dia. bears S.22°W. 33 lks. mkd: T31S R8W S18 BT
- A fir, 18" dia. bears N.66°W., 21 lks. mkd: T31S R8W S7 BT

Lorne V. Swearingen - For: Robert Dollar Co. - May 2, 1962 - C.S. File 51/68-6

Corner was found to be in poor condition.
Scribed - 2 BTs & mkd: as follows:
Set - 7/8" hex drill Steel 20" in the ground for the corner.
36" Fir S.58½°E. 23.2 ft was ref & scribed S17 R4186 BT (Orig. BT for this quad has fallen over & rotted out.)
20" Fir S.45°W. 24.3 ft was ref & scribed S18 R 4186 BT (Orig. BT for this quad. is in place but is a 12" Fir Snag with most the orig. bark scribing obliterated by old cruising chopping but the BT scribing is plainly vis. at base.
The orig. BT in the SW quad. is now 36" and since it has grown so rapidly, all evidence of the orig. bark scribing gone.
The orig. BT in the NE quad has old cruiser chopping marks which has nearly obliterated the orig. bark scribing, but with close scrutiny, orig. marks found above chopping.
BTs were referenced with a compass and chain, mag. dec. used was 19½°.

BLM dependent resurvey by Charles E. Akin, Jr., Cadastral Surveyor, under Group No. 819, surveyed Aug./Sept. 1972 - (DCSO Records Vol. 36 Page(s) 14933-4)

The cor. of secs. 7, 8, 17, & 18, perpetuated and recorded by Swearingen, in 1962, monumented with an iron rod, 1" dia., firmly set, protruding 5" above ground, from which the remains of the original bearing trees:

- A root hole, bears S.22°W., 33 lks., with a down fir alongside, 16" dia., with illegible scribe marks visible on bark blaze.

continued next page

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 200500

PRIMARY CORNER DESCRIPTION Cor Secs 7, 8, 17, & 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A root hole, bears N.66°W., 21 lks., with a down fir alongside, 38" dia., with fragmentary scribe marks visible on bark blaze, and bearing trees marked by Swearingen

A fir, 37" dia., bears S.52°E., 34 lks., with healed double blaze.

A sawed fir stump, 20" dia., bears S.49°W., 38 lks., with scribe marks BT visible on opened blaze.

At the corner paint

Set an iron post, 28" long, 2½" dia., 22" in the ground, directly atop the iron rod, with brass cap mkd.

T 31 S R 8 W
S 7 | S 8
S 18 | S 17
1973

from which new BTs

A fir, 26" dia. bears N.75°E., 77 lks. mkd: T31S R8W S8 BT

A fir, 32" dia., bears N.2°W., 50 lks. mkd: T31S R8W S7 BT

No other suitable BTs available within limits.

Mark Smalley - For: Roseburg Forest Prod. - Dec. 13. 1996 - C.S. 65/13-9J

Found - 1973 BLM CAD. IPBC.
27" Fir, N.75°E., 77 lks. good partially healed scribe visible.
37" Fir, N.2°W., 50 lks. good healed
37" Fir Stump, S.52°E., 34 lks. with metal cap
20" rotten Fir stump, S.49°W., 38 lks.
New BTs- 6" Fir, S.48°W., 36.3' scribed "S 18 BT"
6" Fir, S.1°E., 35.6' scribed "S 17 BT"

Ron Quimby - Crew: N. Fromdahl, J Leonard & R. Olsen - 2/2015 - C.S. File 65/87-18

Condition report only
Found - BLM brass cap
27" D.Fir stump N.75°E., 51.9 ft. good scar.
41" D.Fir stump S.52°E., 23.5 ft. good scar (metal cap)
9" D.Fir S.7°W., 35.6 ft. good scar (Rec. S.1°E)
9" D.Fir S.57°W., 36.3 ft. good scar (Rec. S.48°W)
37" D.Fir N.5°W., 32.0 ft. good scar.
Compass decl. 15½°E.