

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 4; & 33, T30-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 456 dated July 28, 1882 (DCSO records Vol. 17 Page(s) 7309)

Set a Fir post 3 ft. long, 3" in dia., 18" in the ground for the ¼ sec. cor. mkd. ¼ S on the N. side, from which

A Fir 14" dia., bears N.12°E., 21 lks. dist. mkd. ¼ S BT.

A Fir 14" dia., bears S.6°W., 14 lks. dist. mkd. ¼ S BT.

BLM Resurvey by C. Albert White, Harold D. Corbin Cadastral Surveyor and Donald R. Beck, Surveying Technician, Under Group #446, Surveyed Nov. 1960/Sept. 1962 - (DCSO records Vol. 31 Page(s) 13193)

The ¼ sec. cor., determined at record bearing and distance from the original bearing trees:

A Fir 20" dia., bears N.12°E., 21 lks. mkd. ¼ S on bark blaze. Remarkd ¼ S33 BT.

A Fir 22" dia., bears S.6°W., 14 lks. mkd. ¼ S on bark blaze. Remarkd ¼ S4 BT.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

T 30 S R 8 W

¼ $\frac{S\ 33}{S\ 4}$

T 31 S

1962

BLM Resurvey by Charles E. Akin, Jr., Cadastral Surveyor under Group #819, Surveyed Aug/Oct. 1973 - (DCSO records Vol. 37 Page(s) 15226)

The ¼ sec. cor., monumented with an iron post 2½" dia., firmly set, protruding 6" above ground with brass cap mkd. in 1962, from which the original bearing trees, remarked by White and Corbin in 1962:

A Fir 22" dia., bears N.12°E., 21 lks., with healed blaze.

A root hole bears S.6°W., 14 lks., with a down Fir alongside 22" dia., with healed blaze.

and a new bearing tree:

A W.Fir 9" dia., bears S.6°W., 29½ lks., mkd. ¼ S4 BT.

Gerald Nygren - For: Seneca Jones Timber - 4/2015 - M169-26

Found - 1962 BLM brass cap

1882: 29" D.Fir N.12°E., 13.9'

New - 10" D.Fir bears S.35°W., 22.1', scribed "¼ S4 BT"

continued next page

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 4; & 33, T30-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2972, surveyed May 2020/Feb2021 - (DCSO records Vol. 59 Page(s) 23947-8)

The ¼ sec. cor. of secs. 4 and 33, reported by Akin in 1972; perpetuated by Nygren, in 2015; monumented with an iron post, 2½" dia., firmly set, projecting 7" above ground, with a brass cap (properly) mkd.

from which the bearing tree reported by Akin, Jr.

A fir, 30" dia., bears N.12°E., 13.9 ft., with a healed blaze. (Original)

and the remains of a bearing tree mkd. by Nygren

A fir stump, 10" dia., bears S.39¼°W., 22.1 ft., with scribe marks S4 and other illegible scribe marks visible on partially healed blaze.

and a new bearing tree

A cedar, 4" dia., bears S.82°E., 147.2 ft., mkd. X BT.

Each new BT has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center & each monument established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post. Alum. Angle iron driven alongside each monument.