

PRIMARY CORNER DESCRIPTION Sec. Cor. for 24 & 25; 19 & 30, T31-7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8031)

-----  
Set a stone 16x14x12, 10" in the ground, marked two notches on S. and four notches on N. angles for cor. to secs. 19, 24, 25 and 30, from which

- A Fir 26" dia. bears N.66°E., 62 lks. mkd. T31S R7W S19 BT
- A Fir 14" dia. bears S.65°E., 12 lks. mkd. T31S R7W S30 BT
- A Fir 28" dia. bears S.45°W., 60 lks. mkd. T31S R8W S25 BT
- A Fir 20" dia., bears N.42°W. 20 lks. mkd. T31S R8W S24 BT

Douglas Co. Surveyors Office - John M. Powell, Frank Jones and Cliff Stone, crew - Dec. 1966 - C.S. File 54/36-7

-----  
Found - Stone at corner, 4 notches North, 2 notches South.  
26" now 34" D.Fir N.66°E., 40.9 ft., no scribe visible, old face faint.  
14" now 20" D.Fir S.65°E., 7.9 ft., bark scribe faint.  
28" now 34" D.Fir S.45°W., 39.6 ft., bark scribed.  
20" now 24" D.Fir N.42°W., 13.2 ft., bark scribed.

Set Brass cap at cor. mkd: County Surveyors Office  
T 31 S  
R8W S 24 | S 19 R7W  
S 25 | S 30  
1966

Reblazed and rescribed:  
20" D.Fir S.65°E., 7.9 ft. scribed T31S R7W S30 CSBT  
34" D.Fir N.66°E. 40.9 ft scribed T31S R7W S19 CS BT

Cor. Fd. and used in BLM Resurvey by James E. Jelley and James J. Carlson, Cadastral Surveyors, under Group #899, surveyed Aug. 1976/Nov. 1977 - (DCSO records Vol. 41 Page(s) 16190-91)

Mark Smalley - For: Roseburg Resources -1/2002 - M 139-70

-----  
Found - 1966 Douglas County Surveyors brass cap on an iron pipe.  
26" Fir N.42°W. 13.2' snag scribe visible (OBT)  
37" Fir N.66°E. 40.9' scribe not visible face split (OBT)  
22" Fir S.65°E. 7.9' partial scribe visible (OBT)  
46" Fir S.45°W. 39.6' bark scribe not visible (OBT)  
Scribed- 7" Fir S.50°E. 41.9' "S 30 BT"

continued next page

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 700300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 24 & 25; 19 & 30, T31-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ron Quimby - Crew: J. Leonard and N. Fromdahl - 2/2014 - C.S.  
File 65/82-25

-----

Condition Report only

Found - DCSO brass cap (properly marked)  
44" D.Fir N.66°E., 40.9 ft. visible scar.  
26" D.Fir S.65°E., 7.9 ft. visible scar.  
8" Fir stump 2' high S.50°E., 41.9 ft. good scar.  
50" Fir, S.45°W., 39.6 ft. good scar.  
26" Fir stump N.42°W., 13.2 ft. badly burnt.

Note - Area badly burnt 8/2013  
Compass decl. 15½°E.