

PRIMARY CORNER DESCRIPTION NE tsp. Cor. (NE cor. Sec. 1)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William H. Byars, Deputy Surveyor, under Contract #448, dated June 13, 1882 - (DCSO records, Vol. 19 Pgs. 8034-35)

Set a Live Oak post 4 ft. long, 4" sq., 24" in the ground, marked T30S R7W S31 on NE. face; T31S R7W S6 on SE. face; T31S R8W S1 on SW. face; T30S R8W S36 on NW. face; also six notches on the angles of the same for the cor. to Tps. 30 and 31, S. Rs. 7 and 8 W. from which

A Laurel 6" dia., bears N.10°E., 35 lks. dist. mkd. T30S R7W S31 BT.

A Live Oak 5" dia., bears S.70°E., 32 lks. dist. mkd. T31S R7W S6 BT.

A Live Oak 6" dia., bears S.40°W., 43 lks. dist. mkd. T31S R8W S1 BT.

A Laurel 5" dia., bears N.70°W., 13 lks. dist. mkd. T30S R8W S36 BT.

Fd. and used in W.H. Byars survey, contract #450, dated July 28, 1882 - (DCSO records, Vol. 17 Pg. 7249)

GLO survey by Gerald A. Sorrels, U.S. Surveyor, under Group #36, surveyed March/April 1918 - (DCSO records Vol. 17 Page(s) 7287-88) and duplicated info. in Vol. 27 Pgs. 11611-12)

The cor. which is located by reference to the bearing trees. At the exact cor. point

Set an iron post, 3 ft. long, 3" dia., 24" in the ground, for cor. of Tps. 30 and 31 S. Rs. 7 and 8 W., with brass cap mkd.

| | |
|------|-----|
| T30S | |
| R8W | R7W |
| S36 | S31 |
| S1 | S6 |
| T31S | |
| 1918 | |

from which

A Madrona 10" dia., bears N.36°E., 34 lks. dist. mkd. T30S R7W S31 BT. (Old BT)

A Live Oak 8' dia., bears S.75°E., 41 lks. dist. mkd. T31S R7W S6 BT. (Old BT)

A Fir 30" dia., bears S.78°W., 67 lks. dist. mkd. T31S R8W S1 BT (New BT)

A Live Oak 7" dia., bears N.23°W., 33 lks. dist. mkd. T30S R8W S36 BT. (New BT)

(Cont. Next Page)

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 700700

PRIMARY CORNER DESCRIPTION NE Tsp. cor. (NE. cor. Sec. 1)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Jim Halterman, crew - Feb. 1964 - C.S. File 53/40-53

Found - Brass cap at corner and all bearing trees. SW. BT, now rotted stump.

New BT - 6" R.Fir bears S.29°W., 4.5 ft. scribed S1 T31S R8W CS BT.

Fd. OK Dec. 1981 by H. Johnstone - M 89-79