

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 7; & 12, T31-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

**ON THE COUNTY LINE - CHECK WITH COOS COUNTY
FOR POSSIBLY MORE INFORMATION**

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page 8178)

Set a Basalt stone 16x12x5 ins., 12" in the ground mkd. ¼ on W. side for ¼ cor., from which
A Hemlock 18" dia., bears N.58°E., 30 lks. mkd. S7 ¼ S BT.
A Hemlock 30" dia., bears N.85°W., 66 lks. mkd. S12 ¼ S BT

C.S. Lehmanowsky - For: Coos Bay Lumber Co. - Aug. 27, 1954 - C.S. File 54/32-98

I marked new BT for the E. 1/4 cor. sec. 12, T31S R10W. Original corner rock in place; original BTs destroyed by logging operations and fire. For this corner, I mkd. 72" Fir S.73°00'W., dist. 33.0 ft.

Douglas Co. Surveyors Office - John M. Powell, and crew - May 1967 - C.S. File 54/32-81

Found - No trace of original stone or trees.
72" D.Fir, now stump S.73°W., 33.0 ft. scribe visible "¼ BT".

Unrecorded iron pipe at corner.

Set Brass cap at cor. mkd: County Surveyors Office
R T 31 S R
10 ¼ S 12 | S 7 9
W 1967 W

New BTs- 5" Hemlock S.23°W., 30.2 ft. mkd. ¼ S CS BT.
26" Cedar stump S.12½°E., 37.1 ft. mkd. ¼ S7 CS BT
This corner lies in bottom of small ravine, running N. & S. (This cor. previously renewed and recorded in Coos County)

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - 3/2/2015 - C.S. File 65/87-53

Found - 1967 2½" brass cap on a 1¼" O.D. iron pipe, 0.9' tall, in good condition and fairly solid in a mound of stones, cap is oriented N.30°E. We also find a 2" iron pipe, unrecorded, fd by Powell in 1967, 0.8' tall, in good condition and solid in the ground, top is belled out 0.2' east of BCIP. At the BCIP **we record a reading** of 42°53'21.8" and 123°49'08.8" from our hand held Gamin. **We set** a D.Fir post 3' north and paint the top in blue. The following measurements are taken from te BCIP monument.

continued next page

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 7; & 12, T31-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

1954: 64" D.Fir stump, S.72°30'W., 32.51' to heart center. We find a chopped out face, but no visible marks. The stump has been burned and has no remaining bark. **We paint** the face and "BT" in blue. Fair cond.

Note - We searched for BTs set by Powell and fd the following:
The 5" hemlock at S.23°W., 20.2' and the 26" cedar stump at S.12°30'E., 37.1' are both gone. We find an old damaged Douglas Co. tag on the ground near the called location for the SW BT, but no sign of the hemlock.

New - 22" D.Fir stump, S.53°E., 9.24' to a spike and Coos Co. washer driven in at heart center. We chop an "X" into the face and paint the "X" and face in blue. We attach a yellow Coos Co. tag.
18" D.Fir stump, N.41°W., 22.50' to a spike and Coos Co. washer driven in at heart center. We chop an "X" into the face and paint the "X" and face in blue. We attach a yellow Coos Co. tag.
17" D.Fir stump, S.20°W., 20.86' to a spike and Coos Co. washer driven in at heart center. We chop an "X" into the face and paint the "X" and face in blue. We attach a yellow Coos Co. tag.
Dec 17°E