

PRIMARY CORNER DESCRIPTION Wit. Cor. S. 6, T31-9; and S. 1 T31-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page(s) 8179)

Intersect cliffs, course N.30°W. and S.30°E., impassable; marked a Chinquapin 5" dia., R9W S6 on E.; T31S W C on S.; R10W S1 on W. faces, with 6 notches on E.; S.; and W. faces for the witness cor. of T31S R9 and 10 W., from which

A Fir 60" dia., bears S.32°E., 27 lks. dist. mkd. T31S R9W S6 WC BT.

A Fir 30" dia., bears N.63°W., 56 lks. dist. mkd. T31S R10W S1 WC BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - Nov. 1965 - C.S. File 53/53-38

Found - 60" Fir stump S.32°E., 17.8 ft., opened, found "BT".

30" Fir N.63°W., 37.0 ft., found this tree to be N.63°W., 32.0 ft. Did not find any scribing on this snag.

Set Brass cap at cor. W.C. mkd: County Surveyors Office

	T31S	
	W.C. To	
R	_____	R
10	S 1 S 6 9	
W	1965	W

New BTs- 14" Chinquapin bears S.42°W., 47.6 ft., scribed T31S R9W S1 CS BT.

7" Laurel S.26°E., 65.6 ft. scribed T31S R10W S6 CS BT.

This corner is located right on top of ridge next to steep bluffs.

(4/2/2001 revised the stamping of the cap from orig. notes.)

Douglas Co. Surveyors Office - Larry "Ed" Monrean, Deputy - 4/2/2001 - BLM Opinion file C.S. File 63/166

Contacted Dan Berry at Portland BLM, by phone.

Not sure where the NW corner section 6 would be located.

- According to Berry the plat in Portland shows a "WC" at point at 69.00 chains ("intersect Cliffs")
- The south line of sec. 31 in T30-9 is 4 chains longer than N. line of sec. 6 in T31-9.
- On original plat (in Portland) the NW corner sec. 6 falls 4 chains East of Southwest corner Sec. 31.
- Point on range line 2.71 chains south of Twsp line is marked W.C.

Cont.

PRIMARY CORNER DESCRIPTION Wit. Cor. S. 6, T31-9; and S. 1 T31-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Coos County Surveyors Office - Michael Dado, Surveyor - Crew:
Matthew Martin & Bill Hales - March 6, 2015 - C.S. File
65/87-57

Found - 2½" brass cap on a 1¼" O.D. iron pipe, 0.8' tall, in
good condition and solid in the ground, surrounded
by a mound of sandstone rocks. We set a W.Cedar
post 3' north and paint the top in blue. Monument
is located 7' west of steep and deep rock bluff.
Lat & Long per hand held Gamin is 42°54'33.1" and
123°49'10.1"

1901: 33" D.Fir burned stump, S.32°E., 19.50' to
heart center. We find no marks or tags. We paint
"BT" and a band around the stump in blue. Poor
Condition.

1901: 28" D.Fir remains N.60°W., 32.88' to heart
center. We find no marks or tags. We paint the
wood ring in blue. Poor

1965: 5" dead Madrone snag with live sprouts at the
bottom, S.24°30'E., 65.80' to right side center.
We find over grown finishing nails up high, the
snag being solid, but burned and hollow. We
paint the face and a band around the snag in
blue. FAIR CONDITION.

1965: 22" Chinkapin low cut stump, S.45°W., 47.19'
to heart center. We find no marks or tags. We
paint the top in blue. FAIR

New - 22" D.Fir stump, S.19°W., 38.52' to a spike and
Coos County washer driven in at heart center. We
chop an "X" in the face and paint the "X" and the
top of the stump in blue and attach a yellow Coos
County tag.

17" D.Fir stump, S.69°30'W., 15.92' to a spike and
Coos County washer driven in at heart center. We
chop an "X" in the face and paint the "X" and
top of the stump in blue and attach a yellow
Coos County tag.

Decl. 17°E