

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 17 Page(s) 7383)

-----  
Marked a Chinquapin 10" dia., for cor secs. 31, 32, 5 and 6, from which

- A Chinquapin 12" dia., bears N.25°E., 44 lks. dist.
- A Chinquapin 12" dia., bears S.20°E., 36 lks. dist.
- A Fir 15" dia., bears S.80°W., 17 lks. dist.
- A Fir 5" dia., bears N.18°W., 54 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #613, dated April 29, 1893 (DCSO records Vol. 17 Page(s) 7399)

-----  
I find a Chinquapin stump 3 ft. high, greatly decayed at the ground, mkd. with 5 notches on E. and 1 notch on W. edges: There are other surveyors marks on this stump but they are burned out by fire so that they cannot be distinguished. The witness trees are all burned except one, which is lying upon the ground mkd. T31S R9W S5 BT. The stump of this tree is a Chinquapin 12" dia. which bears S.20°E., 36 lks. dist. I therefore mark 4 new witness trees.

At cor. point, I set a stone 14x10x8 ins., 9" in the ground for cor. to secs.5, 6, 31 and 32, mkd. with 1 notch on W. and 5 notches on E. edges, from which

- A Fir 30" dia., bears N.44°E., 65 lks. dist. mkd. T30S R9W S32 BT.
- A Fir 30" dia., bears S.22°E., 65 lks. dist. mkd. T31S R9W S5 BT.
- A Fir 34" dia., bears S.21½°W., 46 lks. dist. mkd. T31S R9W S6 BT.
- A Fir 8" dia., bears N.60¼°W., 36 lks. dist. mkd. T30S R10W S31 BT. (*Typed notes from DCSO office, shows R10W - probably should be R9W*) V.Laugen, June 1997

Survey by Forest LaFlamme - For: Georgia Pacific Corp. - Aug. 12, 1963 - C.S. File 51/265

-----  
Found - Original stone at corner.  
Orig. Fir 30", N.44°E., and the Fir 30" S.22°E., are both snags.  
Orig. Fir 34" S.21½°W., is now a short stub, badly decayed.

No evidence of the original 8" Fir.  
I drive a 1¼" pipe at the South side of the original stone and scribe:  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 5 & 6; 31 & 32 T30-9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

8" D.Fir S.60°W., 34.4 ft. "S6 BT 473"  
 10" Oak S.51°E., 20.4 ft. "S 5 BT".

Douglas Co. Surveyors Office - John M. Powell, and crew -  
 Nov. 1965 - C.S. File 53/53-37

-----  
 Found - 1¼" I.Pipe and original stone.  
 8" D.Fir now 11", S.60°W., 34.4 ft. scribed S6 BT  
 10" Oak now 10", S.51°E., 20.4 ft., scribed S5 BT.  
 (This tree is a Chinquapin.)

Set Brass cap at cor. mkd: County Surveyors Office  
 T 30 S R 9 W  
     S 31 | S 32  
     S 6 | S 5  
 T 31 S R 9 W  
 1965

No other trees available to scribe.

Douglas Co. Surveyors Office - Stephen J. Flause, Deputy -  
 Wit: T. Plouff; K. Mosley - April 7, 1981 - C.S. 61/19-31

-----  
 Found - A 1965 DCSO brass cap properly mkd. on a 1" I.P.  
 firmly set, protrudes 18½" above ground.  
 A 1¼" I.P. protrudes 18" from the ground on the S.  
 edge of brass cap.  
 A 14x10x8" stone is set on the W. side of the brass  
 cap. Stone is mkd. with 5 notches on its E.  
 edge, no marks found on the W. edge, broken.  
 (Rec. 5 notches on E., 1 notch on W.)  
 An iron fence post protrudes 42" from ground on the  
 SW. edge of the brass cap.  
 A search is made for the original BTs. None are  
 found. (1855)  
 1893 BT, a Fir snag 30 ft. tall and 30" DBH, bears  
 S.22½°E., 43.2 ft., face measurement. No scribing  
 or definite blaze marks are found but this tree  
 agrees reasonably well with 1893 Fir, 30" bearing  
 S.22°E., 42.9 ft.  
 1893 BT, 34" Fir now a rotted 30", 12" tall burned  
 Fir stump bears S.21½°W., 32.3 ft. No blazes or  
 scribe marks visible.  
 NW BT, 1893, is searched for but not found.  
 An 8" D.Fir now a 12" DBH D.Fir, bears S.60°W., 34.4  
 ft. Tree has a well healed single blaze. No  
 scribing visible.

(Cont. Next Page)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A 10" Oak now a 12" DBH Chinquapin bears S.51°E., 20.4 ft. Tree has a partially healed single blaze with the scribing S5 BT visible.  
Found monument position is accepted.  
No other suitable bearing trees are available.  
All found trees are tagged with DCSO bearing tree tags.

Douglas Co. Surveyors Office - L.E. Monrean; Randall Smith, crew - Sept. 21, 1992 - C.S. File 64/32-8  
-----

Found - 2½" dia. DCSO brass cap on 1½" O.D. Iron pipe, protruding 18" above ground.  
14" x 10" x 8" stone with 5 notches on E. edge is found on top of ground along W. edge of DCSO BC/IP.  
1¼" I.D. iron pipe protruding 18" above ground found along SE. edge of DCSO BC/IP.  
Metal fence post along S. edge of BC/IP.  
30" now 37" dia. 30 ft. high D.Fir snag with previously opened blazes, no scribing visible, bears S.22°E., 44.5 ft. (Rec. S.22°E., 43.2 ft. dist. is a face measurement)  
34" now decayed Fir stump, no blazes or scribing visible, bears S.21½°W., 32.3 ft. (agrees w/rec.)  
30" now 30" dia. 3 ft. high D.Fir stump with a fully healed blaze, bears N.44°E., 42.9 ft. (agrees w/rec)  
8" now 14" dia. D.Fir with a fully healed blaze, bears S.60°W., 34.4 ft. (agrees w/rec.)  
10" Oak now 15" dia. Chinquapin with small healed blaze 5 ft. above ground and a rotted out center bears S.51°E., 20.4 ft. (agrees w/rec.)  
New BTs- 6" dia. Chinquapin double blazed and scribed "T31S R9W S5 CS BT" bears S.30°E., 15.4 ft.  
5" dia. Chinquapin double blazed and scribed "X BT" bears N.42°E., 19.8 ft.