

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 240400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 17 & 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #727, dated December 20, 1900 - (DCSO records Vol. 19 Page(s) 8229)

Set a fir post, 4 ft. long, 4" sq. 24" in the ground, mkd S17 1/4 S on N & S20 1/4 S on S faces for the 1/4 secs cor. from which
A fir, 24" dia., bears N.54°W., 62 lks., mkd: S17 1/4 S BT.
A fir, 30" dia., bears S.5°E., 43 lks., mkd: S20 1/4 S BT.

Clifford A Stephens - For: Coos Head Timber Co - March 1959 - C.S. file 51/178 & M20-16

Post gone but find both BTs in good condition.
Set new post & 3/4" gal. iron pipe for the 1/4 cor. from which:
A Fir 26" in dia. brs. S.06°E., 28.4 Ft, (BT tag on face)
A Fir 28" in dia. brs. N.56°W., 40.8 Ft
Both BTs original and in good state of preservation.

Jack E. LaFlamme, LS 378 - For: Georgia Pacific - March 1990 - C.S. File 63/104-7

Set - I set a 5/8" iron rod with yellow plastic cap for the 1/4 sec. corner between secs. 17 and 20
From Which:
The orig. 30" Fir BT S.5°E., 43 lks which is now 40" with a BT tag
The orig. 24" Fir BT, N.54°W., 62 lks has been bulldozed out.
A 3/4" I.P. bears N.82°E., 5.3 ft. from the corner.
I Scribe: "1/4 S17 BT 378" on a 6 ft. fir N.29°E., 12.7 ft. to the center.
I chop a low "X" on the Orig. BT. I also set an iron fence post 0.4 ft. North of the corner.