

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Cor Secs 9, 10, 15, & 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co Surveyors Office - Randall W Smith, Deputy -
Stephen Flause - John Pike - Oct. 8, 1992 - C.S. 64/32-19

Found - ¾" I.D. IP firmly set protrudes 7" on Northerly edge
of found brass cap monument.

A 2½" dia. brass cap on a 1⅜" dia. I.Pipe firmly
set and protrudes 5" from ground. (1967 DCS0)
Orig. BT, a Fir 30" dia., now a 40" DBH D.Fir with
a fully healed single blaze bears S.39°E., 43.5
ft. (Rec. S.42°E., 52.8 ft., a possible slope
face measurement)

18" Fir now a rotted and broken 7 ft. tall Fir stob
with possible face axe marks visible (no
scribing) bears S.40°W., 31.1 ft. (Rec. S.40°W.,
30.4 ft.) 1961

40" Fir now a roothole of a fallen and out of
position Fir bears approx. S.71°W., 25.8 ft. 1961

48 D.Fir now a 54" DBH D.Fir with a fully healed
single blaze bears S.02°E., 34.9 ft. (Rec.
S.02°W., 34.9 ft.) 1967

New BTs- 50" dia. 4 ft. tall D.Fir stump with an "X" axed in
the bark facing the corner position, bears
N.88°E., 38.9 ft. (A Georgia Pacific metal tag on
stump has a dist. of 36.5 ft., possibly a face
measurement)

5" DBH D.Fir blazed & scribed "X BT" bears N.57°W.,
20.9 ft.

Monument is on steep N'ly slope just North of a clear cut old
growth boundary running East-West. Monument is approx. 250±
East Southeast & 150 ft. above an improved BLM Road

Fd. Ok by C. Sweeden, Jan. 2003 - M141-39