

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 34 & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W.H. Byars under contract #727, dated December 20, 1900 - (DCSO records Vol. 19 Page(s) 8191)

Set a fir post, 24" long, 4" sq., 24" in the ground, marked S35 on E S34 ¼ S on W for ¼ sec. cor. from which
A fir, 8" dia., bears N.70°E., 24 lks., mkd: S35 ¼ S BT.
A chinquapin, 5" dia., bears N.70°W., 15 lks., mkd: S34 ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones, C. Stone & J. Brady - Feb/March 1967 - C.S. File 54/32-19

Found - Orig. 5" Chinq. N.70°W. 9.9 ft Tree has been opened. Orig. 8" now 20" D.Fir N.70°E., 15.8 ft., shows faint scar.
Set brass cap at cor. mkd: COUNTY SURVEYORS T31S R9W OFFICE 1967 ¼ S 34|S 35
New BT - 15" D.Fir N.76°W., 16.0 ft. mkd: ¼ S34 CS BT.
Reblazed & rescribed -
20" D.Fir N.70°E., 15.8 ft. mkd: ¼ S35 CS BT.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - Oct. 1992 - C.S. File 64/32-14

Found - 1967 DCSO brass cap on a 1½" Iron Pipe, protruding 14" above ground.
8" now 30" dia. D.Fir with a fully healed double blaze bears N.65°E., 15.8 ft. (Rec. N.70°E., 15.8 ft.) Orig. BT)
5" now 10" dia. 2 ft high broken & rotted Chinquapin stump rotted blazes, no scribing found, bears N.70°W., 10.4 ft. (Rec. N.70°W., 9.9 ft. dist. possible blaze measurement)(orig.)
15" now 23 dia. D.Fir with a fully healed double blaze bears N.73½°W., 16.0 ft. (Rec. N.76°W., 16.0 ft.)
New BTs- 6" D.Fir double blazed and scribed "¼ S35 CS BT" bears N.5½°E., 11.0 ft.
9" Chinquapin double blazed and scribe "¼ S34 CS BT" bears S.77°W., 9.0 ft.

FD. Ok by D.Edwards, Jan. 2003 - C.S. File 65/46-1

continued next page

1

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 34 & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Francis J. Simon, Cadastral Surveyor under Group #2325, surveyed July/Nov. 2010 - (DCSO records Vol. 57 Page(s) 22762)

The ¼ sec. cor. of secs. 34 & 35, perpetuated by the Douglas County Surveyor's Office, in 1967, and further perpetuated by the Douglas County Surveyor's Office, in 1992; monumented with an iron post, 1½" dia., firmly set, projecting 14" above the ground, with brass cap (properly) mkd.

from which the remaining original bearing tree

A fir, 31" dia., bears N.65¼°E., 16.4 ft., with a healed blaze. (Record, N.70°E., 15.8 ft.)

and a BT mkd. by the Douglas County Surveyor's Office in 1967

A fir, 28" dia., bears N.74¼°W., 16.1 ft., with a healed blaze.

and BTs mkd. by the Douglas County Surveyor's Office in 1992

A fir, 10" dia., bears N.5¼°E., 10.7 ft., with a healed double blaze.

A chinquapin, 10" dia., bears S.76½°W., 8.8 ft., with scribe marks 1/4S34CS visible on partially healed double blaze.