

PRIMARY CORNER DESCRIPTION AP on So. bdy. Sec. 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor, under Contract #474, dated May 10, 1883 - (DCSO recs C.S. 64/76-2)

A Fir 18" dia., which I mark $\frac{1}{4}$ S on N. side for the $\frac{1}{4}$ sec. cor. from which

A Fir 24" dia., bears East, 13 lks. dist. mkd. $\frac{1}{4}$ S BT.

A Fir 30" dia., bears West, 11 lks. dist. mkd. $\frac{1}{4}$ S BT.

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page 8169)

Old $\frac{1}{4}$ sec. cor. which is a tree standing, mkd. and witnessed as per description furnished by the surveyor general.

GLO Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 29 Page(s) 12188)

Intersect the old $\frac{1}{4}$ cor. of sec. 2, which is a Fir tree, 18" dia., marked and witnessed as described by the surveyor general. I change this cor. to an Angle Point, destroying all marks on the cor. and remarking AP on N. side, from which

A Fir 28" dia., bears S.77°E., 15 lks. mkd AP BT. (Old BT)

A Fir 30" dia., bears S.87°W., 15 lks. mkd. AP BT (Old BT)

Douglas Co. Surveyors Office - John M. Powell, and crew - April/May 1967 - C.S. File 54/32-70

(This A.P. lies 38.0 ft. East of $\frac{1}{4}$ cor. Sec. 2 only, T32-9)
Found - 18" D.Fir Corner tree, now 21", opened, "AP BT" visible.

28" now 34" D.Fir S.77°E., 9.9 ft., shows good scar.

30" now 36" D.Fir S.87°W., 9.9 ft., shows good scar.

Set $\frac{3}{4}$ " x 30" Iron rod on North side of corner tree.

All BTs tagged and OK.

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - 3/28/2011 - C.S. File 67/36-13

Found - 18" Fir mkd " $\frac{1}{4}$ S" on North face then markings destroyed in 1916 and rescribed "AP" on north face. Now 23" D.Fir with fully healed single blaze on north side. 1883

$\frac{3}{4}$ "x30" iron rod protruding 10" above ground bears N.19°E., 1.2 ft. from center of root crown of the tree mentioned above (rec. is "set on north side") 1967

continued next page

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 562100

PRIMARY CORNER DESCRIPTION AP on So. bdy. Sec. 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Center of root crown of AP tree bears S.89½°E., 34.0 ft. (1916 rec. S.89½°E., 35.0 ft.) from N¼ cor. T32S R09W SEC 2 "ONLY"

A 24" fir, now a 33" D.Fir with fully healed single blaze, fully healed high line blaze and timber cruiser marks; bears S.77°E., 9.90 ft. (as recorded in 1916) 1883

A 30" fir, now a 35" D.Fir with fully healed single blaze and fully healed high line blaze; bears S.87°W., 9.90 ft. (As recorded in 1916)

New - A 7" DBH Tan Oak scribed "T32S R9W AP S2 CS" "BT" on double blaze; bears S.7½°W., 56.3

Note - Monument is on a steep east facing hillside. An old clear cut with mix re-growth of Oak + Fir to the north and old growth fir and mixed hardwood to the South.

Compass decl. 16°E.