

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 17 Page(s) 7381)

Set ¼ sec. post, from which
A Fir 10" dia., bears N.10°W., 5 lks. dist.
A Fir 24" dia., bears S.85°E., 40 lks. dist.

Douglas Co. Surveyors Office - John M. Powell, and crew -
Nov. 1965 - C.S. File 53/53-34

Found - 10" D.Fir, down and rotten, N.10°W., 3.3 ft.
24" D.Fir, down and rotten, S.85°E., 26.4 ft. Open
tree for scribe, found "BT".

Set Brass cap at cor. mkd: County Surveyors Office
T 30 S
R9W $\frac{S}{S} \frac{36}{1}$
T 31 S

New BTs- 8" Cedar N.13°E., 27.7 ft. scribed T30S R9W ¼ S36 CS
BT.

5" D.Fir S.37°W., 72.0 ft. scribed S1 CS BT.

This corner is located in bottom of small ravine.

Kris DeGroot - For: Roseburg Resources - 6/2001 - M 137-13

Found - 1¼" IP by Powell, DCSO, in 1965, firmly set flush
w/ground on a steep east slope, 10 ft. west of
bottom of ravine w/¾" brass cap properly stamped.
8" Cedar scribed "T30S R9W ¼ S36 CS BT" uprooted by
felled trees and slid out of position into a
ravine. No evidence of the orig. position.

9" D.Fir bears S.37°W., 71.5 ft. with healed double
blaze. (Rec. S.37°W., 72.0 ft.)

New BT - 18" D.Fir bears N.83°30'W., 30.0 ft. scribed "¼ S36
BT"

Note- All new BTs have double blazed faces w/brass washer
stamped "PLS 1941" nail into the lower blaze.
Bearings are taken to the center of the tree at
the root crown & distances are measured to a nail
in the root crown at the center of the tree all
BTs have a 6" red band painted around the tree &
the blazed face painted red & BT signs nailed to
the tree.