

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 700140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 36; & 31, T31-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 456 dated July 28, 1882 (DCSO records Vol. 19 Page(s) 8103)  
-----  
Set a Fir post 3 ft. long, 3" sq., 20" in the ground, marked 1/4 S on the W. side for the 1/4 sec. cor., from which  
A Fir 24" dia., bears N.42°E., 24 lks. dist. mkd. 1/4 S BT.  
A Fir 5" dia., bears West, 13 lks. dist., mkd. 1/4 S BT.

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page(s) 8238)  
-----  
1/4 sec. corner gone, one witness tree standing.  
Set a Cedar post 4 ft. long, 4" sq., 24" in the ground mkd. S31 1/4 S on E. and S36 1/4 S on W. faces, from which  
A Fir 30" dia., bears N.42°E., 24 lks. dist. (the old tree) marked 1/4 S BT.  
A Fir 8" dia., bears S.50°W., 25 lks. dist. mkd. S36 1/4 S BT.

Lorne Swearingen - For: Robert Dollar Co. - April 15, 1960 - C.S. File 51/68-2  
-----  
Found to be in poor condition.  
The orig. BT in sec.31 was bark scribed and had been burned until the scribing was almost invisible.  
The BT in section 36 was rotted away and only the stump hole remaining.  
Set a 7/8" hex drill steel 20" in the ground for the quarter corner, from which  
6" D.Fir N.61°W., 26.1 ft. was referenced and scribed S36 1/4S 4186 BT.  
36" D.Fir N.42°E., 15.8 ft. (old BT) referenced and scribed 1/4 S 4186 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - Jan. 1967 - C.S. File 54/36-81  
-----  
Found - 7/8" drill steel at 1/4 corner.  
Orig. 24" D.Fir now 30", N.42°E., 15.8 ft., orig. bark scribe "1/4" and rescribe "1/4S BT". This BT is leaning badly with windfall against it.  
6" now 8" D.Fir N.61°W., 26.1 ft., shows good scar.  
New BT - 6" D.Fir S.68°E., 4.8 ft. mkd. 1/4 S31 CS BT.

Fd. 7/8" drill steel & 2 BTs, David Edwards, 5/2009 - M159-23