

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24; 18 & 19, T31-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 456 dated July 28, 1882 (DCSO records Vol. 19 Page(s) 8105-06)

Set a Fir post 4 ft. long, 4" sq., 24" in the ground, mkd. T31S R8W S18 on the NE.; S19 on the SE.; R9W S24 on the SW.; and S13 on the NW. faces; also 3 notches on the S. and N. angles of same, for the cor. to secs. 13, 18, 19 and 24, from which

- A Fir 10" dia., bears N.64°E., 12 lks. dist. mkd. T31S R8W S18 BT.
- A Fir 22" dia., bears S.52°E., 40 lks. dist. mkd. T31SR8W S19 BT.
- A Fir 36" dia., bears S.74°W., 35 lks. dist. mkd. T31S R9W S24 BT.
- A Fir 15" dia., bears N.40°W., 29 lks. dist. mkd. T31S R9W S13 BT.

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page(s) 8240-41)

Post gone, witness trees standing and agree with notes furnished by the Surveyor General.
Set a Fir post 4 ft. long, 4" sq., 24" in the ground, mkd. T31S S18 on NE.; R8W S19 on SE.; R9W S24 on SW.; and S13 on NW. faces; with 3 notches on the N. and S. angles.
The witnesses are thos furnished in the notes.

BLM Resurvey by C. Albert White, Harold D. Corbing Cadastral Surveyor and Donald R. Beck, Surveying Technician, Under Group #446, Surveyed Nov. 1960/Sept. 1962 - (DCSO records Vol. 31 Page(s) 13184-85)

The Sec. Cor., determined at record distance from the remaining original bearing trees:

- A Fir 22" dia., bears N.54°E., 12 lks. dist., scribe marks visible on partially healed blaze. (Rec. brg. N.64°E.)
- A Fir 30" dia., bears S.52°E., 40 lks. dist., scribe marks visible on bark blaze. Remarkd T31S R8W S19 BT.
- A rotted Fir stump 36" dia., bears S.69°W., 36 lks. dist., no marks remain. (Rec. brg. S.74°W.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

(Cont. Next Page)

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 700400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24; 18 & 19, T31-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

T 31 S
R 9 W | R 8 W
S 13 | S 18
S 24 | S 19
1962

from which new bearing trees:

A Fir 62" dia., bears N.26½°E., 63 lks. dist., bark scribed T31S R8W S18 BT.

A Fir 25" dia., bears S.32°W., 54 lks. dist., mkd. T31S R9W S24 BT.

A Fir 10" dia., bears N.88°W., 100 lks. dist. mkd. T31S R9W S13 BT.

Corey M. Woodruff - For: Plum Creek Timberlands, LP - Dec. 2007 - M155-17

Found - BLM BCIP per V. 31 Pg. 13184
59" fir stump bears N.30°E., 40.5'
28" fir bears N.54°E., 8.0'
27" fir snag bears S.52°E., 26.6'
7" fir bears S.15°W., 14.6'
23" fir bears N.88°W., 66.2'

Fd. by C. Woodruff, 6/2010 - M161-7

Ron Quimby - Crew: N. Fromdahl, J. Leonard & R. Olsen - 2/2015 - C.S. File 65/87-13

Condition Report only
Found - BLM brass cap
60" Fir stump N.30°E., 40.5 ft. good scar
30" Fir N.54°E., 8.0 ft. good scar.
28" Fir snag remnants only down S.52°E., 26.6 ft.
8" Fir S.15°W., 14.6 ft. good scar.
26" Fir N.88°W., 66.2 ft. good scar.
Compass decl. 15½°E.