

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 5 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Leland P. Lovejoy - For: Mr. L.E. Gilliam - completed March 18, 1953 - C.S. File 41/159

-----  
Found corner monuments as shown on map. Set 3/4" G.I. Pipe for 1/4 sec. corner monument of sec. 5, in accordance with procedure prescribed by law.

Douglas Co. Surveyors Office - John M. Powell, and crew - July 25, 1968 - C.S. File 54/71-1

-----  
Found - 3/4" Iron pipe (prorated by Leland P. Lovejoy #262, see map filed as C.S. File 41/159. No trees set)  
New BTs- 6" W.Fir S.28°E., 19.4 ft. mkd. 1/4 S5 CS BT.  
7" W.Fir S.38°W., 16.6 ft. mkd. 1/4 S5 CS BT.  
Cor. lies at fence corner, fences E & S, also 159 ft. West of SE Cor. Sec. 32, T31-1.

Survey by Kurt Weaver, #1679 - For: U.S. Forest Service - Feb. 1980 - C.S. File 58/176-34

-----  
Found - The 3/4" GIP as set by Lovejoy.  
8" W.Fir bears S.39°03'W., 18.0 ft. (Rec. S.38°W., 16.6 ft.)  
8" G.Fir bears S.31°00'E., 19.0 ft. (Rec. W.Fir, S.28°E., 19.4 ft.)  
2" GIP with a 2 1/2" B.C. at the sec. cor. for secs. 32 & 33, T31S R1W bears S.89°52'48"E., 158.37 ft.  
I SET a 2" x 30" G.I.P. with a 2 1/2" brass cap over found pipe exposed 16" in a mound of stone and marked: T31S R1W  
1/4 \_\_\_\_\_  
S 5  
T32S R1W  
SL 1679 1980

John Ransom, USFS - Jonathan Drew - 12/2013 - C.S. 65/85-28

-----  
Found - 2 1/2" brass cap (properly mkd) on 2 1/4" iron pipe, projecting 3" above the ground.  
13" Fir (S.38°W.) (15.6 ft) healed single blaze.  
13" Fir (S.28°E.) (19.4 ft) healed single blaze  
Brass cap (S.89°20'28"E.) (158.46 ft) section corner for 33 & 32 only  
**( ) = record measurement per RM3-37**  
No new accessories established  
Measure dist to SW BT to determine which rec matches the tree best. Conflicting records red paint applied to BT faces & a 6" band at head height, BTs include BT & survey monument tags Cont.

TOWNSHIP 32 RANGE 01 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 5 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Brush cleared around monument and to BTs  
"LAND LINE" flagging tied on monument & guard posts  
Note - Corner falls on north slope under a barbed wire a  
few feet east of a large fir tree fence corner.  
Park at dispersed campsite on south side of FS  
road 150 just prior to first cattle guard, walk  
south to fence line then west to corner.  
Maintain line .5 miles south.

Adam DeGroot - For: USFS - Oct 2019 - M171-69A&B  
-----

Found - A 2¼" iron post by Weaver, in 1980 per C.S. File  
58/176-34, firmly set and projecting 8" above  
ground in an 18" diam. stone mound, with a 2 1/2"  
brass cap (properly) mkd:

BTs by DCSO IN 1968 -

A 13" G.Fir bears S.31°E., 18.9 ft w/healed dbl  
blaze (S.28°E., 19.4 ft-DCSO 1968) (S.31°00'E.,  
19.0 ft-Weaver 1980 )

A 14" W.Fir bears S.38°'15'W, 15.5 ft w/healed dbl  
blaze (S.38°W., 16.6 ft-DCSO 1968) (S.39'03'W.,  
18.0 ft-Weaver 1980)

New RM - A 5/8"X30" iron rod w/2" alum. cap mkd. "BTS  
SURVEYING INC RM 1 PLS 89398" bears  
N.31°00'03"W., 19.67 ft

The section corner of S32/S33 bears S.89°50'26"E., 158.28 ft  
(line of sight)

A 6"x10" split cedar fence corner of fences east and south  
bears S.50'E., 2.0 FT

Fd. OK by DCSO (SJF & JL) 6/3/2020 - C.S. File 67/46-33

Lat: 42.828683450 Long: -122.844203217