

TOWNSHIP 32 RANGE 01 POINT IDENTIFIER # 400400

PRIMARY CORNER DESCRIPTION Cor. Secs 15, 16, 21, & 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Rufus S. Moore, Deputy Surveyor, under contract 475 dated July 3, 1883 - (DCSO records Vol. 19 Page(s) 8261)

Set a basalt stone 18x18x12", 12" in the ground for cor. of secs. 15, 16, 21, & 22 at a point about 150 ft. below last spring branch mkd with 3 notches on S & E edges, from which
A fir, 6" dia., bears N.68°E., 9 lks. mkd: T32S R1W S15 BT
A fir, 4" dia. bears S.60°E., 21 lks. mkd: T32S R1W S22 BT
A fir, 6" dia. bears S.28°W., 10 lks. mkd: T32S R1W S21 BT
A fir, 6" dia. bears N.42°W., 20 lks. mkd: T32S R1W S16 BT

BLM Dependent resurvey by Hans W Thielsen, under Group #318, surveyed Aug/Sept 1955 - (DCSO records Vol. 28 Page(s) 12133)

Point for the cor. of secs. 15, 16, 21, & 21 proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 36 long, 2" dia., 30" in the ground, with brass cap marked:
T32S R1W
S 16 | S 15
S 21 | S 22
1955
from which
A fir, 13" dia., bears N.59¾°E., 37 lks., mkd: T32S R1W S15 BT.
A fir, 23" dia. bears S.6½°E., 94 lks mkd: T32S R1W S22 BT
A fir, 28" dia., bears S.41½°W., 31 lks., mkd: T32S R1W S21 BT.
A fir, 20" dia. bears N.19°W., 7 lks. mkd: T32S R1W S16 BT

Douglas Co. Surveyors Office - Gary Langlitz - P. Earle - 6/4/1974 - C.S. File 56/51-16

Found - One BT remaining, all other BTs and the brass cap have been destroyed by construction of a skid trail.
The corner point, located at record bearing & distance from the NE BT marked by Cadastral Engineers in 1955:
A 13" now 16" D.Fir bears N.59¾°E., 24.4 ft., w/scribing "32S R1W S15 BT" visible on partially healed blaze.
Falls on a steep slope.
We set - Brass cap as a witness corner, 30.0 ft. North of the true corner mkd. COUNTY SURVEYORS T32S R1W
OFFICE Wit. Cor.
1974 S 16 | S 15
S 21 | S 22
30 Ft. South to Cor.
We mark the following bearing trees for the witness corner:
continued next page

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

13" D.Fir bears N.82°W., 9.0 ft. scribed "WC T32S R1W S16
CS BT"
36" D.Fir bears N.53°E., 55.6 ft. scribed "WC T32S R1W S15
CS BT"

Douglas Co. Surveyors Office - Stephen J. Flause - Mike
Koch - Sept. 11, 2012 - C.S. File 67/36-23

Found - No evidence of orig. stone fd.
1955 BLM: A 2½" dia., brass cap (properly mkd) on a
2" I.D. x 36" log concrete filled, iron pipe is
fd loose on ground surface in a skid rd cut-bank
slide with no discernible position.
A reference monument (witness cor. per DCS0 1974) is
fd. A 2½" dia., brass cap (properly mkd) on a 1"
I.D. iron pipe firmly and plumbly set, protruding
6" above ground. (WC N 30' from true corner)
From the 1955 resurvey corner position as determined
from the above fd. reference monument, evidence
of one 1955 renewal BT is fd; all other BTs would
have been cut-bank slide.
A fir 13" dia., now a 23" dia., D.Fir with a fully
healed double blaze; bears N.59¾°E., 24.4 ft. (as
per rec.)
From the location of the 1974 reference monument the
2 BTs established to witness this position are fd
A 13" D.Fir now a 20" dia., D.Fir with a fully
healed double blaze; bears N.82°W., 9.0 ft. (as
per rec.)
A 36" D.Fir now a 36" dia., D.Fir with a fully
healed double blaze; bears N.51½°E., 55.6 ft.
(rec. N.53°E., 55.6 ft.)
New - Using the fd. 1974 reference monument and the one
fd. 1955 resurvey BT the location of the 1955
corner monument is determined. The monument
position falls in hard bedrock in a steep cut-
bank. The 1955 BC/IP monument cannot be set here;
instead a 1½" long "MAG" nail with a 9/16" dia.,
top is driven perpendicularly into the bedrock,
to be left protruding approximately ½" and have
its top center at the corner position.
The 1955 BC/IP monument is lain horizontally on
ground next to the reference monument BC/IP
(could be reset at true corner position in
future)
These accessories reference the "MAG" nail position
i.e. the 1955 resurvey section corner
continued next page

TOWNSHIP 32 RANGE 01 POINT IDENTIFIER # 400400

PRIMARY CORNER DESCRIPTION Cor. Secs. 15, 16, 21, & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A 25" DBH D.fir scribed "T32S R1W 15 CS" "BT" on a double blaze; bears N.35½°E., 39.0 ft.
A 5" dia., D.Fir marked "X" "BT" on a high-low blaze; bears N.78¼°W., 18.1 ft.
Note - Corner falls near bottom of steep southeast slope in cut-bank of an old skid road running NE'ly following near the bottom of a small stream canyon also running NE'ly.
Compass decl. 15½°E.