

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Rufus S. Moore, Deputy Surveyor, under contract 475 dated July 3, 1883 - (DCSO records Vol. 19 Page(s) 8256)

Set a maple post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., about 200 ft. below spring branch, marked 1/4 S on W side; from which

A fir, 6" dia., bears East, 13 lks., mkd: 1/4 S BT

A fir, 6" dia., bears N.62°W., 23 lks., mkd: 1/4 S BT.

BLM Dependent resurvey by Hans W Thielsen, under Group #318, surveyed Aug/Sept 1955 - (DCSO records Vol. 28 Page(s) 12131)

The 1/4 sec. cor. of secs. 10 & 11, determined at the record bearing & distance from the orig. BTs:

A fir, 18" dia., bears East, 13 lks., with marks BT uncovered.

A partially rotted fir stump, bears N.62°W., 23 lks. with no remaining marks.

At the corner point

Set an iron post, 36" long, 1" dia., 30" in the ground, with brass cap marked:

1/4
S 10 | S 11
1955

from which new BTs

A R.Fir, 18" dia., bears S.8 1/2°E., 26 lks., mkd: 1/4 S11 BT.

A R.Fir, 14" dia., bears S.72 1/4°W., 26 lks., mkd: 1/4 S10 BT.

Gerald Nygren - For: USFS - July 1989 - C.S. 63/85-28

Found - 1" iron pipe with 1955 GLO 2 1/2" brass cap extended 5" above ground.

18" D.Fir bears N.85°E., 8.4 ft. (healed blaze) Orig.

26" D.Fir bears S.8 1/4°E., 16.7 ft (healed blaze) 1955

22" D.Fir stump bears S.72°W., 16.6 ft. (healed blaze) 1955

New BT - A 6" D.Fir bears N.64°W., 8.9 ft. scribed "1/4 S10 BT" with 1/2" dia., brass washer mkd: "LS 1035" nailed to lower blaze.