

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Charles L. Campbell, Deputy Surveyor, under Contract #747 dated May 5, 1902 - (DCSO records Vol. 20 Page(s) 8312

The true point for 1/4 sec. cor. falls on a ledge, 15x10x8 ft. above ground, on which I cut a cross at the exact cor. point, for 1/4 sec. cor. mkd 1/4 on N side of cross, from which

A fir, 30" dia., bears N.41°E., 85 lks., mkd: 1/4 S11 BT.

A fir, 12" dia., bears S.95°W., 71 lks., mkd: 1/4 S14 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Vincent Perron - 8/6/1970 - C.S. File 54/117-11

Found - "X" on top of rock ledge, as called for in field notes.

15'x10'x8' above ground & "1/4" chiseled 3" to N of "X"

Orig. 30", now 36" Fir, alive, N.41°E. 56.1 ft., scribe visible on rehealing blaze., good condition. We Tag.

Orig. 12", now 20" Fir, alive, S.85°W. 46.9 ft. (Rec. S.95°W), scribe visible on rehealing blaze. Good condition.

We are unable to set Standard Brass Cp at Corner Point so we Drove, "PK" Nail in Center of "X" and Rechiseled old marks. New BT - 8" W.Fir S.23°W. 9.7 ft. mkd: "1/4 S14 CS BT"

Corner Point is located nearly verticle over Diamond Creek, course N.20°E. & old call to west of 118 ft. looks O.K. We do not measures. Walls on both sides of creek are nearly verticle & composed of solid rock.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - J. Heritage - 7/23/1973 - C.S. File 56/34-15

Found - "X" on rock ledge as called for in orig. field notes, 15'x10'x9' and both orig. BTs, plus BT as recorded in 1970

PK nail was loose that was set in center of "X"

Set - We drill hole in center of "X" and set Brass cap mkd.

Douglas County T32S R2W

Surveyors 1/4 S11 S 14

Office

1973

Note - We do not mark new as both orig's & 1970 ren. BT are alive and in good cond.