

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 24

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by Charles L. Campbell, Deputy Surveyor, under Contract #747 dated May 5, 1902 - (DCSO records Vol. 19 Page(s) 8298</p> <p>-----</p> <p>Set an ironstone 24x15x10", 18" in the ground for 1/4 sec. cor. mkd. 1/4 on N face, from which</p> <p> A fir, 24" dia., bears S.60°E., 45 lks., mkd: 1/4 S24 BT.</p> <p> A fir, 60" dia., bears N.21°W., 43 lks., mkd: 1/4 S13 BT.</p>	
<p>Douglas Co Surveyors Office - M Lenora Lading - Gary L Langlitz - Debbie L Stewart - July 8, 1976 - C.S. 59/18-4</p> <p>-----</p> <p>Found - A 24x15x10" ironstone mkd "1/4" on north face, from which</p> <p> A 24" now 36" fir bears S.60°E., 29.7 ft. Tree is alive with well healed blaze.</p> <p> A 60" now 72" fir stump bears N.21°W., 28.4 ft. Fd. no trace of scribing.</p> <p>Set - At true corner point a 1x36" IP with brass cap stamped:</p> <p> DOUGLAS CO. SURVEYOR</p> <p> T32S R2W</p> <p> 1/4 <u>S 13</u></p> <p> S 24</p> <p> 1976</p> <p>Placed orig. stone north of brass cap</p> <p>New - 5" hemlock bears S.73°W., 12.3 ft. scribed "1/4 S24 CS BT" in double blaze.</p>	
<p>Glenn S. Baughman - For: USFS - Dec. 1976 - M56-69; M56-70; M56-68</p> <p>-----</p> <p>Found - 1976 Douglas County Surveyors brass cap.</p> <p> 36" W.Fir bears S.60°E., 29.7 ft.</p> <p> 72" Fir (stump) bears N.21°W., 28.4 ft.</p> <p> 5" Hemlock bears S.73°W., 12.3 ft.</p> <p>New BT - 6" Fir bears S.75°W. 22.6 ft scribed T32S R2W S24 BT</p>	
<p> </p>	