

TOWNSHIP 32 RANGE 02 POINT IDENTIFIER # 679700

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 31 only, T31-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7460)

Set ¼ sec. post, from which
A Fir 18" dia., bears N.50°E., 27 lks. dist.
A Fir 30" dia., bears S.30°E., 14 lks. dist.

Tied into corner in GLO Survey by Rufus S. Moore, Deputy Surveyor, under Contract #475, dated July 3, 1883 - (DCSO records Vol. 19 Page(s) 8248-49)

GLO survey by Fred Mensch, under Special Instructions, dated June 1922 - (DCSO records Vol. 18 Page(s) 7581-82)

Intersect the old ¼ sec. cor. which is Fir 18" dia., with marks overgrown; from which

A Fir 30" dia., bears N.50°E., 27 lks. dist. mkd. ¼ S BT.
(Old BT)

A Fir 40" dia., bears S.30°E., 14 lks. dist. mkd. ¼ S BT.
(Old BT)

I now change this cor. to refer to sec. 31 only, and obliterate the marks on the bearing tree S. of line.

Re-mark the tree corner, ¼ S31 on N. face; from which

A Fir 36" dia., bears N.8°W., 64 lks. dist. mkd. ¼ S31 BT.
(New BT.)

Remark the NE. tree, ¼ S31 BT.

Douglas Co. Surveyors Office - John M. Powell, Deputy - Frank Jones; W. Penley, crew - July 1968 - C.S. file 54/71-7

Found - 30" now 36" D.Fir N.50°E., 17.8 ft., shows good scar with parts of scribing visible, also faint bark scribe "¼SBT".

Corner tree and SE. BT, down and out of place. A lot of trees fell out of the same area and slid down the mountain.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 1 W

¼ S 31

T 32 S R 2 W

1968

New BT - 18" D.Fir N.21°E., 55.8 ft. mkd. ¼ S31 CS BT.

This corner lies 15.8 ft. W. of township cor. for T32-2