

TOWNSHIP 32 RANGE 02 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 24; & 19, T32-1

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Rufus S. Moore, Deputy Surveyor, under Contract #475, dated July 3, 1883 - (DCSO records Vol. 19 Page(s) 8245)

-----  
Set a Fir post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on W. face, from which  
A Dogwood 3" dia., bears East, 15 lks. dist. mkd. ¼ S BT  
A Fir 6" dia., bears N.80°W., 9 lks. dist. mkd. ¼ S BT.

Glenn S. Baughman - For: U.S. Forest Service - Dec. 1976 - M 56-69

-----  
Set 2½" x 30" I.P. with brass cap stamped: "T32S R2W S24 R1W S19 ¼ S 1976 OLS 536"., from which  
8" D.Fir bears N.29°W., 18.4 ft. scribed T32S R2W S24 BT.  
6" Cedar bears S.2°E., 3.1 ft. scribed T32S R1W S19 BT.

Maurice Farr, LS #1181; - For: U.S. Forest Service - Leonard Herzstein & Randy Lopez, crew - July 15, 1985 - C.S. File 62/26

-----  
CORNER REPORT ONLY  
Found - 2½" dia. I.P., firmly set, flush with a 2 ft. mound of stone with a 3" dia. brass cap set by Baughman in 1976.  
A steel fence post bears East, 3.9 ft. with U.S.F.S. signs #54-2 and 54-9 attached, as a guard post.  
A 7" Cedar S.02°E., 3.1 ft. with scribe marks "T32S R1W ¼ S19" visible on partially healed double blaze with a ¾" brass cap washer stamped "LS 536" nailed flush to lower blaze.  
A 10" D.Fir N.29°W., 18.4 ft. with healed double blaze.  
An unrecorded BT by Baughman in 1976, a 12" D.Fir S.51°E., 20.2 ft. with scribe marks "T32S R1W S19 BT" visible on partially healed double blaze with a ¾" brass washer stamped "LS 536" nailed flush to lower blaze.

Fd. Ok by Jack L. Brewen, June 1977 - M116-25

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 24; & 19, T32-1

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM dependent resurvey by Francis J. Simon, Cadastral Surveyor under Group #2007, surveyed April/June. 2002 - (DCSO records Vol. 54 Page(s) 21247)

-----  
The ¼ sec. cor. of secs. 19 & 24, reestablished at proportionate measurement by Baughman, in 1976, utilized by Brewen, in 1977. There is no remaining evidence of the original corner; therefore this point and is accepted as the corner; monumented with an iron post, 2½" dia., firmly set, projecting 3" above the ground, with brass cap mkd.

T 32 S

R 2 W    R 1 W  
S 24    S 19  
      ¼ S  
1976 LS 536

from which remains of bearing trees mkd. by Baughman  
A cedar snag, 7" dia., bears S.2°E., 3.1 ft., with scribe marks R1W ¼ S19 and other illegible marks visible on partially healed blaze.  
A fir, 12" dia., bears N.29°W., 18.4 ft., with a healed double blaze.  
and a bearing tree mkd. by person(s) unknown  
A fir, 15" dia., bears S.47½°E., 19.9 ft., with a healed double blaze.

John Ransom, USFS - Jonathan Drew - 9/2013 - C.S. 65/85-29

-----  
Found - 3" brass cap (properly mkd) on 2½" iron pipe, projecting 1" above a mound of stone  
7" Cedar snag (S.2°E.) (3.1 ft) scribe on part. healed double blaze  
14" Fir (N.29°W.) (18.4 ft) healed double blaze  
16" Fir (S.47½°E.) (19.9 ft) healed double blaze  
( ) = Record per 2002 BLM record

**No new accessories added**

New nails in BT tags and painted faces & 6" band at head height

Brush cleared around monument and to BTs  
"LAND LINE" flagging tied on monument & guard posts

Note - Corner falls on slight east slope about 380 ft north of intersection of two forest roads, one open one closed. And about 150 ft east of RR Gap RD at a small pull-out.  
Property line maintained east .25 miles