

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 18

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 20 Page(s) 8373)</p> <p>-----</p> <p>Set ¼ sec. post, from which A S.Pine, 36" dia., bears N.50°W., 21 lks. A Cedar, 8" dia., bears S.30°W., 16 lks.</p>
<p>GLO survey by Fred Mensch, Deputy Surveyor- Under special instructions dated Aug. 20, 1912 - (DCSO records Vol. 20 Page(s) 8414)</p> <p>-----</p> <p>The ¼ sec. cor. which is a badly decayed post, marked & witnessed as described by the Surveyor General I destroy this cor. and reestablish it in the same place as follows: Set a slate stone 18x10x8", 12" in the ground for ¼ sec. cor. mkd. ¼ on North face, from which A S.Pine, 48" dia., bears N.50°W., 24 lks., mkd: ¼ S7 BT. A Cedar, 10" dia., bears S.30°W., 16 lks., mkd: ¼ S18 BT.</p>
<p>John Madding, Prof. Eng. by Bate Plywood Co. - Nov. 1963 - C.S. File 51/270</p> <p>-----</p> <p>During logging & slash burning, the I.Cedar BT was knocked over & face burned out. The 48" S.Pine BT is now a stump. The 18"x10" stone is at its orig. location. To replace the I.Cedar, I scribed an 18" D.Fir stump S.82°30'W., 9.3 ft. from orig. stone.</p>
<p>Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Aug. 4, 1969 - C.S. File 54/91-41</p> <p>-----</p> <p>Found - 18x10x8 Stone out of ground at ¼ corner. 48" S.Pine, now stump, N.50°W. 15.8 ft., shows good scar. 10" Cedar, now stob, S.30°W. 10.6 ft., scribe visible, "1/ 18". 16" D.Fir S.76°W. 10.2 ft., scribe visible (unrecorded Tree)</p> <p>Set - Brass Cap at Cor. Mkd: County Surveyors T32S R3W Office ¼ S 7 1969 S 18</p> <p>New BT - 10" Cedar N.70°W. 110.2 ft. mkd: "¼ S7 CS BT". This corner lies about 260.0 ft. west of creek in clear-cut unit.</p>