

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 140700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; & 31 of T31-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page(s) 7687)

Set ¼ sec. post, from which
 A Fir 10" dia., bears N.47°W., 25 lks. dist.
 A Fir 10" dia., bears S.22°W., 19 lks. dist.

George J. Wenderoth, Deputy Co. Surveyor - Frank Loso, Wit.
-June 1950 - M 27-15

Found - 20" Fir N.47°W., 16.5 ft.
 16" Fir S.22°W., 12.5 ft.
Drive 1¼" Pipe for corner.

Douglas Co. Surveyors Office - James Byron, Deputy - For:
Doug. Co. Road Dept. - Jan./Feb. 1957 - Road Drawer 48/ Rd.
File #36

Found - 1¼" I.P. at E-W fence line.
 The NW BT good condition, checks for brg. & dist.,
 scribing visible.
 The SW BT down.
I blaze and scribed:
 10" Hemlock S.22½°W., 24.3 ft. "S6 T32S R3W ¼ Cor.
 CS BT.

Terrence O. Nickerson - For: B.L.M. - Oct. 1979 - M 80-71

Set 5/8" Iron rod 24: long, 20" in the ground, from which
 A Fir 10" dia., bears N.30¼°E., 198.0 ft. dist. with spike
 at base.
 A Fir stump 32" dia., bears S.12°E., 327.7 ft. with spike
 at base.

This corner set by proportionate distance, there is no remaining evidence of the original corner or the perpetuation by Wenderoth and the Douglas Co. Surveyors Office. This area is now a cultivated field with all trees and stump removed.

FD. Ok by R. Brown, 2/2009 - M157-10