

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 20 Page(s) 8372)

Set ¼ sec. post, from which
A Fir, 30" dia., bears N.50°E., 27 lks.
A Fir, 18" dia., bears S.72°W., 16 lks.

Douglas Co. Surveyors Office - John M. Powell - 8/20/1969 & 9/1969 - C.S. File 54/91-62 & C.S. File 54/91-76

Reported as not found.
8/20/1969 - Fd. old N-S blazes. Run line from sec. cor. south of ¼ cor. This area has had a burn as all other trees are burnt stobs or down.
9/1969 - 2nd time, looked for.

Malcolm Clark - For: USFS - April 1980 - M83-55 & C.S. File 58/227(n)

Found - 20" Fir snag bears S.72°W., 10.6 ft. (16 lks) shows bark blaze.
30" Fir windfall bears N.52°E., 17.8 ft. (27 lks.) bark scribed "R" "T" & "B"
Set - Alum. cap by proportion, stamped: T32S R3W ¼ S7 S8 1980 RLS 601.
New BTs- 18" D.Fir bears N.85°45'E., 72.9 ft. scribed "T32S R3W ¼ S8 BT"
14" D.Fir bears N.14°40'W., 46.4 ft. scribed "T32S R3W ¼ S7 BT"

Fd. Ok by G. Lang - 7/1995 - M123-79